

PLANT & EQUIPMENT

تقرير الفحص – 2018 تاتا دايو K6DVF

الرقم التسلسلي: KLTK6DVF1JK000008 | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١١٠٩

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
N/A	(Emissions Status (Add blue
Yes	Hill stand aid function
N/A	Horn off-on
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Navigation
Yes	ABS
Yes	Driver bed
N/A	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes	Retarder
N/A	Rear Axle Lifter
N/A	Radio
N/A	TRC
N/A	Camera sensor
Yes	Differential lock
Yes	Advanced emergency brake assist

Truck Cabin Details

Need upholstery	Seat and Arm Support
Need minor service, 2 door lock need replase	Cab Doors & covers
Ok	Controls, Levers



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

1 mirror glass missing, 1 mirror missing, front
glass broken
Not functional
Not functional
Not functional
Not functional
Need service
Need service
Need upholstery
N/A
Start directly from the starter and off directly
from the fuel pump

Windows and Mirrors

Dashboard Screen, Gauges

Warning alarms message

Washer, Wipers

Air Conditioning & Heating System

Cab Floor Covering

Interior, Covers

Passenger Seat

Radio

Starting

Engine & Performance

Mechanical
Doosan DV15TIS
Ok
Ok
Normal
Ok
Ok
Normal
Ok
Ok

Fuel Injection Type

Engine Model

Engine Cooling System

Engine Oil Check

Blowby

Exhaust System & Muffler

Belts & Air/Oil Filters

Smoke

Coolant

Fluid Leaks

Exterior Condition & Visual Inspection

Ok, minor rust
Ok
Ok
Ok, need service
Ok
Ok
Front bumper need repair
Not functional, need 6 bulbs

Chassis, Frames

Frame Stamp Serial Number

Sheet Metal, Covers

Steps, Grab Irons

Paintwork

Cooler Grill

Bumpers

Lights / Batteries



PLANT & EQUIPMENT

Ok
front and rear spring leafs need service
Ok

Fenders
Suspension Springs/Hangers
Suspension Bushings

Power Train

Ok
Ok
Ok
Ok
Ok, minor leak
Ok
Ok
Manual
Ok

Axels/Differentials
Stabilizers, Beams
Rubber Sleeves
Brake Pads/Disks
Compressor
Transfer Gear
Universal Joints
Transmission
Clutch

Truck Limited Functional Test

Not functional
Not functional
Functional
N/A
Functional
Functional
Need service
Functional

Transmission Forward
Transmission Reverse
Steering
Automatic Group Select
Service Brake
Park Brake
Electrics
Retarder

Hydraulics

Functional
Functional, minor leak from lifting cylinder
Ok, right cylinder minor leak

PTO Pump
hydraulic cylinder
cabine lift cylinder & valve

Tires

R60%, L40%
R40%, L40%
R20%, L20%

(%) Axle 1 / RHS mm (%) / LHS mm
(%) Axle 2 Inside / RHS mm (%) / LHS mm
(%) Axle 2 Outside / RHS mm (%) / LHS mm



PLANT & EQUIPMENT

R70%, L40%

(%) Axle 3 Inside / RHS mm (%) / LHS mm

R50%, L60%

(%) Axle 3 Outside / RHS mm (%) / LHS mm

-

Tire Size

L 5400 , W 27500 , H 1400 mm

Ok

Cargo box

Size

Condition

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

