

Inspection report – 2006 Caterpillar TH580B

Location: Dubai, United Arab Emirates | SKU: 1413273

Key Features & Condition

Safety Certification Label	N/A
Axle Based 4WD	Yes (not functional)
Electric Powered	N/A
Equipment Parts Manual	N/A
Electric Operating System	N/A
Horn Function	N/A
Travel Alarm	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Diesel Powered	Yes

Operator Cabin Details

Seat and Arm Support	Need upholstery
control levers, Control swithes	Need change
Dashboard Screen, Gauges	Not functional
Warning alarms message	Not functional
Electrical System	Need full repair
Windows/ mirrors/ Wipers	Front window is cracked
Floor Mates	Ok

Engine

Model	3054E
Injection Type	Mechanical
Leaks	Minor
Oil Condition	Ok
Exhaust Smoke	N/A
Cooling System	N/A
Coolant	Ok, normal water
Sound	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Blow By	N/A
Belts	N/A
Power	Need electrical repair

Exterior Condition & Visual Inspection

Chassis	Ok, minor welding at lifting cylinders pin
Sheet Metal	Ok
Side Doors	Ok, has a crack
Boom Condition	Ok
Boom Linkage / Guides	N/A
Paintwork	Ok, some parts are repainted
Cooler Grill	Ok
Frame Condition	Ok
Outriggers	Not tested need electrical repair
Batteries	Ok

Hydraulic System

Hoses, Lines, Swivel	Ok
Pump And Valve Bloc	Need electrical repair
Steering Cylinder	Need electrical repair
Boom Lift Cylinder(s)	Need electrical repair
Telescopic Boom Cylinders	Need electrical repair
Carriage Tilt Cylinder	N/A
Frame Leveling Cylinders	N/A
Stabilizer Cylinders	N/A
Leaks	Minor

Drivetrain

Transmission	Not tested need electrical repair
Transfer Gear type	Semi-auto
Transfer Case / Drop Box	Not tested need electrical repair
Front / Rear Axle	Not tested need electrical repair

Limited Functional Testing & Operation

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Drive Forward	Not tested need electrical repair
Drive Reverse	Not tested need electrical repair
Steering	Not tested need electrical repair, rear steering need repair
Platform Function Controls	Not tested need electrical repair
Boom Extension	Not tested need electrical repair
Fork angle movment	Not tested need electrical repair
Wheel Bearing	Not tested need electrical repair
Platform control	Not tested need electrical repair
brake system	Not tested need electrical repair
Lifting	Not tested need electrical repair

Tires condition / Type / Size

Axle 1 Right	80% tubeless offroad 15,5/18-24
Axle 1 Left	80% tubeless offroad 15,5/18-24
Axle 2 Right	70% tubeless offroad 15,5/18-24
Axle 2 Left	80% tubeless offroad 15,5/18-24

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

