

## Rapport d'inspection – 2015 Caterpillar 966H

Numéro de série: CAT0966HJBJ601493 | Heure: 27444 | Lieu: Dubai, Émirats arabes unis | SKU: 1019

---

### Key Features & Condition

|                                      |     |
|--------------------------------------|-----|
| Safety Certification Label           | N/A |
| Automatic Lubrication System         | N/A |
| Auxiliary Hydraulic Valve            | N/A |
| Equipment Parts Manual               | N/A |
| Air Conditioning System              | Ok  |
| Hydrostatic Drive System (Hydrostat) | N/A |
| Supplemental Steering System         | Ok  |
| Operator's Manual                    | N/A |
| Emission Compliance Label            | N/A |
| Quick Attachment Coupler             | N/A |
| Load Weighing System                 | N/A |
| Horn Function                        | Ok  |

---

### Operator Cabin Details

|                                   |                        |
|-----------------------------------|------------------------|
| Seat and Arm Support              | Ok                     |
| Cab Doors & covers                | Ok                     |
| Controls, Levers                  | Ok                     |
| Windows and Mirrors               | Ok                     |
| Dashboard Screen, Gauges          | Ok                     |
| Warning alarms message            | 96-3, 351-13, 274-3    |
| Washer, Wipers                    | Ok, rear wiper missing |
| Air Conditioning & Heating System | Ok                     |
| Cab Floor Covering                | Ok                     |
| Cab Structure, Gard               | Ok                     |
| Electrical System                 | Need minor service     |

---

### Engine & Performance

|                     |            |
|---------------------|------------|
| Fuel Injection Type | Electronic |
|---------------------|------------|

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |              |
|--------------------------|--------------|
| Engine Model             | C11          |
| Engine Cooling System    | Ok           |
| Engine Oil Check         | Ok           |
| Blowby                   | Normal       |
| Exhaust System & Muffler | Ok           |
| Belts & Air/Oil Filters  | Ok           |
| Smoke                    | Normal       |
| Coolant                  | Normal water |
| Fluid Leaks              | Minor leaks  |

---

## Exterior Condition & Visual Inspection

|                            |                           |
|----------------------------|---------------------------|
| Main Frame and Lift Arm    | Ok                        |
| Engine Hood                | Ok                        |
| Access Steps and Handrails | Ok                        |
| Exterior Paint Condition   | Ok                        |
| Counterweight Condition    | Ok                        |
| Wheel Fenders              | Ok                        |
| Lights Check               | Ok                        |
| Battery Check              | Ok                        |
| Covers                     | Engine left cover missing |

---

## Power Train Inspection

|                           |                |
|---------------------------|----------------|
| Axles and Differentials   | Ok             |
| Transmission Gearbox      | Minor oil leak |
| Power Train force         | Ok             |
| Transmission Noise Check  | Ok             |
| Universal Joint Condition | Ok             |
| Transfer Gear Type        | Semi- auto     |

---

## Hydraulic System

|                              |                 |
|------------------------------|-----------------|
| Hydraulic Leaks              | OK, minor leaks |
| Lift and Tilt Hydraulic Jack | Ok, minor leak  |
| Steering Hydraulic Jacks     | Ok, minor leak  |
| Hydraulic Pumps and Valves   | Ok              |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Limited Functional Testing & Operation

|                             |                                   |
|-----------------------------|-----------------------------------|
| Steering Function Test      | Ok                                |
| Transmission Operation Test | OK, 2nd front gear not functional |
| Loader Stall Test           | Ok                                |
| Brake System Test           | Ok                                |
| Articulation Movement Check | Ok                                |
| Loader Attachment Pins      | Ok, bucket pins minor loose       |

## Attachments

|                               |                        |
|-------------------------------|------------------------|
| Bucket Width and Capacity     | W3200, H1500, D1000 mm |
| Bucket Bottom Condition       | Minor Damaged          |
| Bucket Edge & Teeth Condition | Ok, no teeth           |
| Bucket Side Condition         | Ok                     |
| Attachment Coupler            | Ok                     |

## Tires Inspection

|                                |                 |
|--------------------------------|-----------------|
| Front Right                    | -               |
| Tire Brand & Size Details      | MAXAM, 26.5R25  |
| Tire Remaining Life Percentage | 70%             |
| Tire Condition Notes           | Good, Tubeless  |
| Wheel Rims & Nuts              | Ok              |
| Front Left                     | -               |
| Tire Brand & Size Details      | ITR, 26.5R25    |
| Tire Remaining Life Percentage | 50%             |
| Tire Condition Notes           | Good, Tubeless  |
| Wheel Rims & Nuts              | Ok              |
| Rear Right                     | -               |
| Tire Brand & Size Details      | MAXAM, 26.5R25  |
| Tire Remaining Life Percentage | 70%             |
| Tire Condition Notes           | Good, Tubeless  |
| Wheel Rims & Nuts              | Ok              |
| Rear Left                      | -               |
| Tire Brand & Size Details      | Advance 26.5R25 |
| Tire Remaining Life Percentage | 70%             |

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Tire Condition Notes  
Wheel Rims & Nuts

Good, Tubeless  
Ok

---

## Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

