

Rapport d'inspection – 2017 Caterpillar 980L

Heure: 20567.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1395264

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Yes
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Implement calibration; fuel water separator is full
Washer, Wipers	Ok, rear wiper is not functional
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Guard	Ok,no Guard
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Model	C13
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok, first step is missing
Exterior Paint Condition	Ok
Counterweight Condition	Ok
Wheel Fenders	Ok
Lights Check	Ok, need 3 bulbs
Battery Check	Ok
Side Doors & Covers	2-missing covers, 1-missing door

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok, second gear is not functional
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi-Auto

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Steering Hydraulic Jacks	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pumps and Valves

Ok

Limited Functional Testing & Operation

Steering Function Test

Ok

Transmission Operation Test

Ok, second gear is not operational

Loader Stall Test

Ok

Brake System Test

Ok

Articulation Movement Check

Ok

Loader Attachment Pins

Ok

Supplemental Steering Test

Ok

Attachments

Bucket Width and Capacity

W3350, H1500, D1250 (5.7 m³)

Bucket Bottom Condition

Ok, armored

Bucket Edge & Teeth Condition

Ok

Bucket Side Condition

Ok

Attachment Coupler

Ok

Tires Inspection

Front Right

-

Tire Brand & Size Details

BKT (29.5R25)

Tire Remaining Life Percentage

70%

Tire Condition Notes

Ok, tiny cuts

Wheel Rims & Nuts

Ok

Front Left

-

Tire Brand & Size Details

BKT (29.5R25)

Tire Remaining Life Percentage

30%

Tire Condition Notes

Some wears, cuts

Wheel Rims & Nuts

Ok

Rear Right

-

Tire Brand & Size Details

BKT (29.5R25)

Tire Remaining Life Percentage

80%

Tire Condition Notes

Ok

Wheel Rims & Nuts

Ok, 1-nut is missing

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Rear Left	-
Tire Brand & Size Details	BKT (29.5R25)
Tire Remaining Life Percentage	40%
Tire Condition Notes	Minor wears, cuts
Wheel Rims & Nuts	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

