

تقرير الفحص – 2016 دوosan DX225LC-9C

الرقم التسلسلي: DXCCEBCAJG0020089 | ساعات: ٥٦٧٩ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٧٢٨

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple And Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System Addblue
N/A	Stabilizer Blade Condition
N/A	Horn

Operator Cabin Details

Ok	Seat And Arm Support
Ok	Cab Doors & Covers
Ok	Control Levers, Control Stick
Ok	Windows And Mirrors
Ok, Some Warn Lights Are Active	Dashboard Screen, Gauges
Ok	Warning Alarms Message
Not Functional	Washer, Wipers
Not Functional	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Need Minor Service	Electrical System

Engine & Performance

Electronic	Fuel Injection System
Doosan DL06	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok, Minor Dents	Main Frame & Track Frame
Ok, Under Swing Cover Is Missing	Protective Covers & Sheets
Ok	Engine Hood
Ok, Left Door Minor Dent	Side Access Doors
Ok	Steps And Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Not Functional	Lights
Need Change	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok, Left Cylinder Minor Leak	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok, Minor Leak	Arm Hydraulic Jack

Performance Analysis

Ok	Boom Pins Condition
Ok	Excavator Self- Drift Test



Ok, Minor Loose	Arm Pins Condition
Ok, Little Noisy	Hydraulic Pump Noise Check
Ok, Minor Loose, Washer Is Missing	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive And Brake Test
Ok	Drive Force Test

Attachments

Bucket	Attachments Model
(W1250, H1000, D800 (Mm	Size
Ok, Minor Dents And Welding	Status
Ok	Coupler Status
N/A	Second Attachments Model
N/A	Size
N/A	Status

Undercarriage

40%	Bushings
Right 70% - Left 50%	Track Shoes
80%	Idlers
Mm 600	:Shoe Width In Mm
Mm 55	:Track Pitch In Mm
40%	Carrier Rollers
30%	Track Rollers
Right 60% - Left 50%	Track Links
Right 70% - Left 50%	Sprocket Segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

