

## تقرير الفحص – 2011 كاتربيلر D7G

الرقم التسلسلي: CAT00D7GV7MB05612 | ساعات: ١٠٥١١ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٩٠

### Key Features & Condition

N/A	Safety Certification Label
N/A	Ground Ripper
N/A	Ripper Control Valve
N/A	Low Ground Pressure Tracks
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Grade Control System
N/A	Equipment Parts Manual
N/A	CAT System One
Yes	Horn

### Operator Cabin Details

Ok	Seat and Arm Support
N/A	Cab Doors & covers
Ok	Controls, Levers
N/A	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
N/A	Washer, Wipers
N/A	Air Conditioning & Heating System
N/A	Cab Floor Covering
N/A	Cab Structure, Gard
Ok	Electrical System

### Engine & Performance

Mechanical	Fuel Injection Type
3306	Engine Model
Ok	Engine Cooling System



Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Ok	Fluid Leaks

## Exterior Condition & Visual Inspection

Ok	Push Frame & Trunnions
Ok	Doors, Covers, and Grilles
Ok	Access Steps & Handrails
Ok	Exterior Paint Condition
Ok	Blade Trunnions & Bushings
Ok	Underbody Protection Plates
Ok	Final Drive Condition
Ok	Fuel Tank, Roof, & Hood Condition
Ok, need 4 bulbs	Lights and Battery Check
N/A	Push Arm Pivot Shaft
N/A	Tilt Linkage Pins & Bushings

## Hydraulic System

Ok	Hydraulic Leaks
Ok	Lift Hydraulic Jacks
N/A	Ripper Lift Hydraulic Jacks
N/A	Tilt Hydraulic Jack
N/A	Angle Hydraulic Jack
N/A	Ripper Angle Hydraulic Jacks

## Limited Functional Testing & Operation

Ok	Push Frame Pins
Ok	Blade Pins
N/A	Ripper Pins
N/A	Equalizer Bar Condition



Ok	Bulldozer Stall Test
Ok	Steering Function Test
Ok, no tilt	Blade Tilt and Lift Test
N/A	Undercarriage Pivot Pins
Ok	Transmission Test
Ok	Brake System Test
Ok	Torque Converter Test

## Blade Inspection

Ok	Blade Base Condition
Ok	Spill Rack Condition
Ok	Blade Front Condition
Ok	Blade Edge Condition

## Undercarriage Inspection

### Right Side Undercarriage Wear

80%	Undercarriage Bushings
80%	Undercarriage Shoes
80%	Front Idler Condition
N/A	Rear Idler Condition
80%	Carrier Roller Condition
80%	Track Links Condition
80%	Sprocket Condition
80%	Roller Condition
N/A	Track Canon Condition

### Left Side Undercarriage Wear

80%	Undercarriage Bushings
80%	Undercarriage Shoes
80%	Front Idler Condition
N/A	Rear Idler Condition
80%	Carrier Roller Condition
80%	Track Links Condition



# المعدات والآليات | تقويم المزادات

80%	Sprocket Condition
80%	Roller Condition
N/A	Track Canon Condition
W610,L250 mm	Track Width Measurement

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

