

تقرير الفحص – 2011 ماسي فيرغسون 6480

الرقم التسلسلي: B160017 | ساعات: ٤٠٦٨ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٠١١

Key Features & Condition

N/A	Safety Certification Label
N/A	Environmental Protection Agency
N/A	A/C
Yes	PTO
Yes	4WED
N/A	All Wheel Steer
Yes	Point Linkage-3
Yes	Drawbar
N/A	Emission Compliance Label
N/A	Horn Function
Yes	Closed Cabin
Yes	CE Specification
Yes	Shift Speed Controller
N/A	Front Axle Suspension
Yes	Cabin Suspension
Yes	Engine Speed Memory Control

Operator Cabin Details

Ok	Seat and Arm Support
Ok, left door glass broken and lock need repair	Cab Doors & covers
Ok	Controls, Levers
Ok, front left mirror missing	Windows and Mirrors
Ok, monitor not functional	Dashboard Screen, Gauges
Error E9151, E9023, air flow sensor, oil pressur, oil temperture	Warning alarms message
Ok, rear not functional	Washer, Wipers
Not functional	Air Condition & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure



Need service

Electrical System

Electronic
SisuDiesel / 6 cyl.Turbo/intercooled
Ok
Ok
Normal
Ok
Ok, filters need change
Normal
Normal water
Minor oil leak from turbo gasket, minor diesel
leak from first injector feed pipe

Engine & Performance

Fuel Injection Type

Engine Model

Engine Cooling System

Engine Oil Check

Blowby

Exhaust System & Muffler

Belts & Air/Oil Filters

Smoke

Coolant

Fluid Leaks

Exterior Condition & Visual Inspection

Ok

Chassis

Ok

Engine Hood

Ok

Steering Linkage

Ok

Access Steps and Handrails

Ok

Exterior Paint Condition

N/A

Sheet Metal

Ok, front right missing

Wheel Fenders

Not functional, 1 missing

Lights Check

Ok

Battery Check

Ok

Rims, Wheel Nuts

Power Train Inspection

Ok

Axles and Differentials

Ok

Transmission Leak

Ok

Power Train force

Ok

Transmission Noise Check

Ok

Universal Joint Condition

Semi-Auto 4 gear

Transfer Gear Type



Hydraulic System

Ok	Hydraulic Leaks
Available, not tested	Remote Hydraulic Controls
Ok	Steering Hydraulic Jacks
Ok	Hydraulic Pumps and Valves
N/A	(Cylinder(s)

Limited Functional Testing & Operation

Ok	Steering Function Test
Ok	Transmission Operation Test
N/A	Cylinder Pins and Bushings
Ok	Braking System Test

% Tires Estimated Remaining Life

-	Front Right
ASCENSO 16,9-28	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
Tubeless / new	Tire Condition Notes
-	Front Left
ASCENSO 16,9-28	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
Tubeless / new	Tire Condition Notes
-	Rear Right
ASCENSO 600/ 65R38	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
Tubeless / new	Tire Condition Notes
-	Rear Left
ASCENSO 600/ 65R38	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
Tubeless / new	Tire Condition Notes

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

