

تقرير الفحص – 2012 ليبيهر LTM 1070-4.2

الرقم التسلسلي: W09484600CEL05368 | ساعات: ١٣٦٧٢ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٠١٣

Key Features & Condition

Yes	CE Labeling
Yes	Automatic Shift
N/A	Semi-Automatic
Yes	Tachograph
N/A	Auto Lube
Not functional	A/C
N/A	Extended Fuel tank
Yes	Retarder
Yes	Rear Axle Lifter
Yes	Axle Steering 2
Yes	Cruise Control
Yes	Air Suspension
Yes	Bluetooth Controller

Truck Cab

Ok	Driver Seat
Ok	Switches, Levers
Ok	Gauges, Warn Lights
Not cooling	Aircon / Heater
Ok	Passenger Seat
Ok	Cab Doors
Ok	Windows, Mirrors
Ok	Wipers, Washers
Ok	Interior, Covers
Ok	Radio

Crane operator cab

Ok	Driver Seat
----	-------------



Ok	Switches, Levers
Ok,hard visual minor sunburnt	Gauges, Warn Lights
Not cooling	Aircon / Heater
Ok	Cab Doors
Ok	Windows
Ok	Wipers
Ok	Interior Covers

Engine

Electrical	Injection Type
LTM 1070-4.2	Engine Model
Ok	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler
Ok	Cooling System
Ok	Smoke, Fume
Normal	Blow By
Ok	Belts, Pulleys
Ok	Coolant Condition

Visual inspection exterior

Ok	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Ok	Lights
Ok	Batteries
Ok	Main Hook

Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams



Ok	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Ok, Automatic	Transmission
N/A	Clutch

Hydraulics / Steering

Ok	Hoses & Lines
Ok	Hydraulic Pump
Ok	PTO
Ok	Steering Cylinders
Ok	Steering Linkage
Ok	Lift Limitation
Ok	Outriggers
Ok	Hook
Ok	Boom Cylinder

Carrier Limited Functional Test

Ok	Transmission Forward
Ok	Transmission Reverse
Ok	Automatic Group Select
Ok	Service Brake
Ok	Park Brake
Ok	Electrics
Ok	Retarder

Crane Condition / Limited Test

Ok	Drive Forward & Back Function
Ok	Controls, Levers Function
Ok	Boom Conditions
Ok	Telescopic Segments Function
Ok	Hydraulic Cylinders Function



Ok	Swing Bearing / Drive Function
Ok	Hose Lines
Ok	Lift Limitations Function
Ok	Hook
Ok	Outriggers Function
Need service	Automatic Outrigger Leveling

% Tires Condition

-	Right
70% Airomax	Axle 1
70% Goodride	Axle 2
70% Goodride	Axle 3
70% Goodride	Axle 4
-	Left
70% Goodride	Axle 1
70% Airomax	Axle 2
70% Goodride	Axle 3
70% Airomax	Axle 4
445/95R25	Tire Size

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

