

تقرير الفحص – 2013 كاتربيلر 226B3

الرقم التسلسلي: CAT0226BESNA00162 | ساعات: ٢٢٨٧٣ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١٠٣٠

Key Features & Condition

N/A	Safety Certification Label
N/A	Operator's Manual
N/A	Equipment Parts Manual
N/A	Air Conditioning System
N/A	Emission Compliance Label
N/A	Closed Cabin
N/A	Horn Function

Operator Cabin Details

Ok, need upholstery	Seat and Arm Support
Ok	Cab Doors & covers
Functional, minor leak	Control Levers, Control Stick
Only rear window, right mirror, and center mirror cracked, left mittor handle not original.	Windows and Mirrors
Fuel gauge need replace	Gauges
N/A	Warning alarms message
N/A	Washer, Wipers
N/A	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Guard
Ok	Electrical System
Ok	Start key
Ok	Main Safty Switch
Not functional	Engine rpmThrottle Lever

Engine & Performance

Mechanical	Fuel Injection Type
C2.2 Serial nom: CYS21623	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Minor	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Normal water	Coolant
Minor Gasket leak	Leaks& seals

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok	Protective Covers & Sheets
Ok, no Lock	Engine Door
Ok	Lights
Ok	Battery Check
Repainted	Exterior Paint Condition

Hydraulic System

Minor leaks	Hydraulic Leaks
Ok	Lift and Tilt Hydraulic Jack
Ok	(Steering Hydraulic Orbital (drive motor
Functional	Hydraulic Pumps and Valves

Limited Functional Testing & Operation

Functional	Drive Function Test
Functional	Skid steer Stall Test
Functional	Brake System Test
Minor Loose	Attachment Pins
Functional	Final Drive Motors Test
Functional	Park Break

Attachments

Bucket	Attachments model
W1530, H700, D400 mm	Size



Ok	Bottom condition
Ok, no teeth	Edge & teeth condition
Ok	Bucket side condition
Ok	Coupler status

% Tires Estimated Remaining Life

40%	Front Right
40%	Front Left
40%	Rear Right
40%	Rear Left
10-16.5	Size
Tube less	Type
Ok, 1 nut missing	wheel Rims & Nuts

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

