

PLANT & EQUIPMENT

تقرير الفحص – 2014 تاتا دايو M9AVF

الرقم التسلسلي: KL3M9AVF1EK000616 | كم: ١٧٦٠٩٢ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١١١٣

Key Features & Condition

N/A	Safety Certification Label
Manual	Automatic Shift
Manual	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
N/A	(Emissions Status (Add blue
Yes	Hill stand aid function
N/A	Horn off-on
N/A	Tachograph
N/A	Auto Lube
Not working	A/C
N/A	Navigation
Yes	ABS
Yes	Driver bed
Yes	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes, not tested	Retarder
N/A	Rear Axle Lifter
N/A	Radio
N/A	TRC
N/A	Camera sensor
Yes	Differential lock
Yes	Advanced emergency brake assist
Yes	Water Tank

Truck Cabin Details

Need upholstery	Seat and Arm Support
-----------------	----------------------



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok, need minor service, no covers , passenger
door doesn't close

Ok

Front glass broken, windows control need
service

Not Functional only water temperature

Not functional

Not functional

Not functional

Need minor service

Ok

Need upholstery

N/A

Cab Doors & covers

Controls, Levers

Windows and Mirrors

Dashboard Screen, Gauges

Warning alarms message

Washer, Wipers

Air Conditioning & Heating System

Cab Floor Covering

Interior, Covers

Passenger Seat

Radio

Engine & Performance

Fuel Injection Type

Engine Model

Engine Cooling System

Engine Oil Check

Blowby

Exhaust System & Muffler

Belts & Air/Oil Filters

Smoke

Coolant

Fluid Leaks

Mechanical

DV15TIS

Ok

Ok, need change

Normal

Minor welding

Need change

Normal

Normal water

Oil sump leaks, minor leak from gasket and
turbo oil pressure

Start directly from the starter and shut down
from the pump throttle

Starting

Exterior Condition & Visual Inspection

Chassis, Frames

Frame Stamp Serial Number

Sheet Metal, Covers

Steps, Grab Irons

Ok, minor rust

Ok

Ok, minor rust

Ok, minor dent



شركة باندي لمزادات ش.ذ.م.م
دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة
هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok

Paintwork

Ok

Cooler Grill

Front bumper need change broken

Bumpers

Drive light broken, need 6 bulbs, batteries
need change

Lights / Batteries

Ok

Fenders

spring leaf minor loose

Suspension Springs/Hangers

4 rear bushings worn out

Suspension Bushings

Ok

Water Tank

Power Train

Ok, diffrentials minor leak

Axels/Differentials

Ok

Stabilizers, Beams

Ok

Rubber Sleeves

Need service

Brake Pads/Disks

Major leak

Compressor

Ok

Transfer Gear

Minor loose

Universal Joints

Manual, need minor electric service

Transmission

Functional

Clutch

Truck Limited Functional Test

Functional

Transmission Forward

Functional

Transmission Reverse

Functional

Steering

N/A

Automatic Group Select

2 Rear boosters need change

Service Brake

Ok

Park Brake

Need minor service

Electrics

Not tested

Retarder

hydraulics

Not functional

PTO Pump

N/A

Water pump



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Not functional,

cabine lift cylinder & valve

Tires

R70%, L70%

(%) Axle 1 / RHS (%) / LHS

R70%, L70%

(%) Axle 2 Inside / RHS (%) / LHS

R70%, L70%

(%) Axle 2 Outside / RHS (%) / LHS

R50%, L60%

(%) Axle 3 Inside / RHS (%) / LHS

R40%, L70%

(%) Axle 3 Outside / RHS (%) / LHS

R30%, L40%

(%) Axle 4 Inside / RHS (%) / LHS

R30%, L30%

(%) Axle 4 Outside / RHS (%) / LHS

Axle1&2 315/80 R 22.5, Axle 3&4 12 R 22.5

Tire Size

Water Tank

7000L

size

Ok

condition

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

