

تقرير الفحص – 2014 تيريكس RT555

الرقم التسلسلي: 1T9T503CEW161848 | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٠١٥

Key Features & Condition

N/A	CE Labeling
N/A	Automatic Shift
YES	Semi-Automatic
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Extended Fuel tank
N/A	Retarder
YES	Axle Steering 2

Truck Cab

Ok	Driver Seat
Ok	Switches, Levers
Ok, 2 gauges are not functional	Gauges, Warn Lights
Not functional	Aircon / Heater
Ok	Cab Doors
Ok	Windows, Mirrors
Ok	Wipers, Washers
Ok	Interior, Covers

Engine

Electrical	Injection Type
CUMMINS_ 6BTA 5.9	Engine Model
Ok	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler
Ok	Cooling System
Normal	SmOke, Fume
Normal	Blow By



Ok
Normal water

Belts, Pulleys
Coolant Condition

Visual inspection exterior

Ok	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Not functional	Lights
Ok	Batteries
Ok	Main Hook
Ok	Auxiliary Hook

Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
N/A	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Semi-Automatic	Transmission
N/A	Clutch

Hydraulics / Steering

Ok, minor leaks	Hoses & Lines
Ok	Hydraulic Pump
Ok	PTO
Ok	Steering Cylinders
Ok	Steering Linkage
Sensor not functional	Lift Limitations
Top pads minor cracks	Outriggers



Ok
Minor rust, minor leak

Hook
Boom Cylinder

Crane Condition / Limited Test

Ok
Ok
Ok
Ok
Functional
Not tested due to a swing lock broken air hose
Swing lock broken air hose (dry)
Sensot not functional
Ok
Ok
Ok
Ok

Drive Forward & Back
Controls, Levers
Boom Function
Telescopic Segments Function
Hydraulic Cylinders
Swing Bearing / Drive
Hose Lines
Lift Limitations
Main Hook Function
Auxiliary Hook Function
Outriggers Function
Park Brake

% Tires Condition

-
30% DRY
60% Ok
-
60% Ok
60% Ok
ROADSTONE _ 26.5--25

Right
Axle 1
Axle 2
Left
Axle 1
Axle 2
Size / Brand

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including



المعدات والآليات | تقويم المزادات

the year of manufacture, operating hours, mileage, compliance, specifications, performance,
.or operating condition of the equipment

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

