

PLANT & EQUIPMENT

تقرير الفحص – 2014 تيريكس RT555

الرقم التسلسلي: 1T9RT503JEW161855 | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ٩٧٦

Key Features & Condition

N/A	CE Labeling
N/A	Automatic Shift
YES	Semi-Automatic
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Extended Fuel tank
N/A	Retarder
YES	Axle Steering 2

Truck Cab

Need upholstery	Driver Seat
Ok	Switches, Levers
Transmission oil pressure guage not functional	Gauges, Warn Lights
Not functional	Aircon / Heater
Ok	Cab Doors
Ok	Windows, Mirrors
Ok	Wipers, Washers
Ok	Interior, Covers

Engine

Electrical	Injection Type
COMMINIS_ 6BTA 5.9	Engine Model
Ok, miner leaks	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler
Ok	Cooling System
Normal	Smoke, Fume
Normal	Blow By



PLANT & EQUIPMENT

Ok
Normal water

Belts, Pulleys
Coolant Condition

Visual inspection exterior

Ok	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Need two bulbs	Lights
Ok	Batteries
Ok	Main Hook
Ok	Auxiliary Hook

Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
N/A	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Semi-Automatic	Transmission
N/A	Clutch

Hydraulics / Steering

Ok/ minor leak	Hoses & Lines
Ok	Hydraulic Pump
Ok	PTO
Ok	Steering Cylinders
Ok	Steering Linkage
Not functional	Lift Limitations
Top pads minor cracks	Outriggers



PLANT & EQUIPMENT

Ok
Minor rust, minor leaks

Hook
Boom Cylinder

Crane Condition / Limited Test

Ok
Ok
Ok
Ok
Minor leaks, minor rust
Ok
Ok
Not functional
Ok
Ok
Ok

Drive Forward & Back
Controls, Levers
Boom Conditions
Telescopic Segments
Hydraulic Cylinders
Swing Bearing / Drive
Hose Lines
Lift Limitations
Main Hook
Auxiliary Hook
Outriggers

% Tires Condition

-
60% Ok
60% Ok
-
60% Ok
60% Ok
ROADSTONE _ 26.5--25

Right
Axle 1
Axle 2
Left
Axle 1
Axle 2
Size / Brand

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.



PLANT & EQUIPMENT

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com