

تقرير الفحص – 2015 كاتربيلر 966H

الرقم التسلسلي: CAT0966HEBJ601213 | ساعات: ٣٣٥٥٢ | الموقع: دبي, الإمارات العربيّة المتّحدة | رقم التعريف: ٩٨٣

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
Yes	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
Yes	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
N/A	Horn Function

Operator Cabin Details

Ok	Seat and Arm Support
Ok, cover is missing	Cab Doors & covers
Ok	Controls, Levers
Ok	Windows and Mirrors
Screen low visibility (sunburnt)	Dashboard Screen, Gauges
Screen low visibility (sunburnt)	Warning alarms message
Ok	Washer, Wipers
Ok, weak cooling	Air Conditioning & Heating System
Ok, minor cut	Cab Floor Covering
Ok	Cab Structure, Gard
Need minor service	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
------------	---------------------



Cat C11	Engine Model
Ok	Engine Cooling System
Ok, need change	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok, normal water	Coolant
Ok	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok, no lift hyd jack and motor	Engine Hood
Ok	Access Steps and Handrails
Ok	Exterior Paint Condition
Ok, minor welding	Counterweight Condition
Ok	Wheel Fenders
Ok, need 4 bulbs	Lights Check
Ok	Battery Check

Power Train Inspection

Ok	Axles and Differentials
Ok	Transmission Gearbox
Ok	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi-auto	Transfer Gear Type

Hydraulic System

Ok	Hydraulic Leaks
Ok, tilt jack minor oil leak, and welded	Lift and Tilt Hydraulic Jack
Ok	Steering Hydraulic Orbital
Ok	Steering Hydraulic Jacks
Ok	Hydraulic Pumps and Valves



Limited Functional Testing & Operation

Ok	Steering Function Test
Ok,4th gear not functional	Transmission Operation Test
Ok	Loader Stall Test
Ok	Brake System Test
Ok	Articulation Movement Check
Ok	Loader Attachment Pins
Ok	Electrical System Check
Ok	Supplemental Steering Test

Attachments

W3100,H1400, D950 mm	Bucket Width and Capacity
Ok	Bucket Bottom Condition
Ok	Bucket Edge & Teeth Condition
Ok	Bucket Side Condition
Ok	Attachment Coupler

Tires Inspection

-	Front Right
TRIANGLE 26.5R25	Tire Brand & Size Details
40%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Front Left
TRIANGLE 26.5R25	Tire Brand & Size Details
40%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Right
TRIANGLE 26.5R25	Tire Brand & Size Details
40%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts



-	Rear Left
TRIANGLE 26.5R25	Tire Brand & Size Details
40%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

