

PLANT & EQUIPMENT

تقرير الفحص – 2015 دوسان DL420A

الرقم التسلسلي: DWGCWLBBVF1010800 | الموقع: Dubai, الإمارات العربية المتحدة | رقم التعريف: ١١٧٢

Key Features & Condition	
N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
N/A	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
N/A	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
N/A	Horn Function

Operator Cabin Details	
Ok, need upholstery	Seat and Arm Support
Ok, need minor maintenance	Cab Doors & covers
Functional, minor leak	Controls, Levers
Ok, right window lock need change	Windows and Mirrors
Ok, oil temperature,rpm,fuel gauges not functional	Dashboard Screen, Gauges
Ok	Warning alarms message
Not functional	Washer, Wipers
Not functional	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure
Need minor service, manual switch-off	Electrical System

Engine & Performance	
Mechanical	Fuel Injection Type



PLANT & EQUIPMENT

DOOSAN DE12TIS

Engine Model

Ok

Engine Cooling System

Ok

Engine Oil Check

Normal

Blowby

Ok

Exhaust System & Muffler

Ok, need change

Belts & Air/Oil Filters

Normal

Smoke

Ok

Coolant

Ok

Fluid Leaks

Ok

Power

Exterior Condition & Visual Inspection

Ok

Main Frame and Lift Arm

Ok

Engine Hood

Ok

Access Steps and Handrails

Ok, repainted

Exterior Paint Condition

Ok

Counterweight Condition

Ok

Wheel Fenders

N/A

Lights Check

Need change

Battery Check

Need minor service

Covers

Power Train Inspection

Ok

Axles and Differentials

Ok, only first gear doesn't change

Transmission Gearbox

Ok

Power Train force

Ok

Transmission Noise Check

Semi auto

Universal Joint Condition

-

Transfer Gear Type

Hydraulic System

Ok, minor

Hydraulic Leaks

Ok, lift minor leaks

Lift and Tilt Hydraulic Jack

Ok

Steering Hydraulic Jacks



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok

Hydraulic Pumps and Valves

Limited Functional Testing & Operation

Functional
Functional, only first gear doesn't change
Ok
Ok
Ok, minor loose
Ok

Steering Function Test
Transmission Operation Test
Loader Stall Test
Brake System Test
Articulation Movement Check
Loader Attachment Pins

Attachments

w3090, H1360, D910 mm
Ok
Ok, no teeth
Ok
Ok, pin lock welded

Bucket Width and Capacity
Bucket Bottom Condition
Bucket Edge & Teeth Condition
Bucket Side Condition
Attachment Coupler

Tires Inspection

-
HUNG-A 26.5 - 25
70%
Ok
Ok
-
HUNG-A 26.5 - 25
40%
Ok
Ok, wheel hub leaks
-
HUNG-A 26.5 - 25
80%
Ok
Ok, wheel hub leaks
-

Front Right
Tire Brand & Size Details
Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts
Front Left
Tire Brand & Size Details
Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts
Rear Right
Tire Brand & Size Details
Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts
Rear Left



PLANT & EQUIPMENT

TIRON

70%

Ok

Ok

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Wheel Rims & Nuts

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com