

PLANT & EQUIPMENT

تقرير الفحص – 2015 نيو هولاند B90B

الرقم التسلسلي: FNH0B90BNFHH01405 | ساعات: ١٩٥٢٨ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١١٦٩

Key Features & Condition

N/A	Safety Certification Label
N/A	Environmental Protection Agency
Not functional	A/C
N/A	Auxiliary Lines
Yes	4WED
N/A	Extended Stick
Yes	Rear Quick Coupler
Yes	All Wheel Steer
N/A	Fork
N/A	Emission Compliance Label
N/A	Horn Function

Operator Cabin Details

Need upholstery	Seat and Arm Support
Ok, left door lock need service	Cab Doors & covers
Ok, outriggers levers hard move	Controls, Levers
front window cracked, the door glass is changed to plastic, and there is UV degradation	Windows and Mirrors
Ok	Dashboard Screen, Gauges
N/A	Warning alarms message
Not functional	Washer, Wipers
Not functional	Air Condition & Heating System
Ok, minor cut	Cab Floor Covering
Ok, 1 interior cover broken	Cab Structure
Need service	Electrical System

Engine & Performance



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة
هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Mechanical
4.5 litre FPT Industrial engine
Ok, minor leak from reservoir tank
Ok, need change
Normal
Ok minor welding, minor hole
Need change
Normal
Ok
Gasket leak, rear cover leak, oil sump leak
Functional

Fuel Injection Type
Engine Model
Engine Cooling System
Engine Oil Check
Blowby
Exhaust System & Muffler
Belts & Air/Oil Filters
Smoke
Coolant
Fluid Leaks
fuel pump & diesel system

Exterior Condition & Visual Inspection

Ok
Ok
Ok
Ok
Ok, minor bend
Ok
Need 4 bulbs
Need change, alternator service
Ok
Ok
N/A
Ok
Ok

Chassis
Engine Hood
Access Steps and Handrails
Exterior Paint Condition
Sheet Metal
Wheel Fenders
Lights Check
Battery Check
Boom
Stick
Stick Extension
Rims, Wheel Nuts
Loader Frame & Hinges

Power Train Inspection

Ok, minor leak from differentials
Minor leak from drive shaft
Ok
Ok
Ok, minor loose
Manual with semi auto control

Axles and Differentials
Transmission Leak
Power Train force
Transmission Noise Check
Universal Joint Condition
Transfer Gear Type



PLANT & EQUIPMENT

Hydraulic System

Ok, minor	Hydraulic Leaks
Ok	Lift and Tilt Hydraulic Jack
Ok	Steering Hydraulic Jacks
minor leak from control valve	Hydraulic Pumps and Valves
Minor leak	Swing Cylinders
Minor leak	Boom Cylinder
Ok	Stick Cylinder
Ok	Bucket Cylinder
N/A	Clamshell Cylinder

Limited Functional Testing & Operation

Functional	Steering Function Test
Functional	Transmission Operation Test
Functional	Loader Stall Test
Functional, need service	Braking System Test
Minor loose	Pins Boom
Minor loose	Pins Stick / Extension
Functional	Rear Bucket Linkage
Functional	Loader Pins & Hinges
Functional	Outriggers & Pads
N/A	Boom Side Tilt

% Attachments Estimated Remaining Life

-	Front Bucket
W2200, H970, D600 mm	Size
Ok	Condition
-	Rear Bucket
W570, H700, D450 mm	Size
Ok	Condition
Ok	Attachment Coupler

% Tires Estimated Remaining Life

-	Front Right
---	-------------



PLANT & EQUIPMENT

OZKA 12.5/80-18

70%

Ok

-

OZKA 12.5/80-18

20%

Big side cut

-

FARMBOY 16.9-28

70%

Ok

-

Marris 16.9-28

40%

Ok, dry

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Front Left

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Rear Right

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Rear Left

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

