

# PLANT & EQUIPMENT

## تقرير الفحص – 2015 نيو هولاند B90B

الرقم التسلسلي: FNH0B90BNFHH01165 | ساعات: ١١٨٢٢ | الموقع: Dubai, الإمارات العربية المتحدة | رقم التعريف: ١١٧٠

### Key Features & Condition

|                |                                 |
|----------------|---------------------------------|
| N/A            | Safety Certification Label      |
| N/A            | Environmental Protection Agency |
| Not cooling    | A/C                             |
| N/A            | Auxiliary Lines                 |
| Yes            | 4WED                            |
| N/A            | Extended Stick                  |
| Yes            | Rear Quick Coupler              |
| Yes            | All Wheel Steer                 |
| N/A            | Fork                            |
| N/A            | Emission Compliance Label       |
| Not functional | Horn Function                   |
| N/A            | Jack Hammer Line                |
| N/A            | Radio                           |
| N/A            | Tools                           |
| N/A            | Operation Manual                |
| N/A            | Greas Pump                      |

### Operator Cabin Details

|                             |                                |
|-----------------------------|--------------------------------|
| Need upholstery             | Seat and Arm Support           |
| Ok, glass need polish       | Cab Doors & covers             |
| Levers need minor service   | Controls, Levers               |
| Front and side glass broken | Windows and Mirrors            |
| Ok                          | Dashboard Screen, Gauges       |
| Ok                          | Warning alarms message         |
| Rear wiper missing          | Washer, Wipers                 |
| Not cooling                 | Air Condition & Heating System |
| Ok                          | Cab Floor Covering             |
| Ok                          | Cab Structure                  |

شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



# PLANT & EQUIPMENT

Need minor service, starts direct from starter

Electrical System

## Engine & Performance

Mechanical  
4.5 litre FPT Industrial engine  
Ok  
Ok, need change  
Minor  
Ok  
Ok  
Minor white smoke  
Coolant  
Minor leak from head gasket, rear cover  
Fuel system need service

Fuel Injection Type  
Engine Model  
Engine Cooling System  
Engine Oil Check  
Blowby  
Exhaust System & Muffler  
Belts & Air/Oil Filters  
Smoke  
Coolant  
Fluid Leaks  
Fuel Pump

## Exterior Condition & Visual Inspection

Ok  
Ok  
Ok  
Ok  
Ok  
Ok  
Ok  
Need 4 bulbs  
Ok  
Ok  
Ok  
Ok  
Ok  
Ok

Chassis  
Engine Hood  
Access Steps and Handrails  
Exterior Paint Condition  
Sheet Metal  
Wheel Fenders  
Lights Check  
Battery Check  
Boom  
Stick  
Stick Extension  
Rims, Wheel Nuts  
Loader Frame & Hinges

## Power Train Inspection

Ok, diffraction minor leak  
Ok  
Ok

Axles and Differentials  
Transmission Leak  
Power Train force



# PLANT & EQUIPMENT

|                            |                           |
|----------------------------|---------------------------|
| Ok                         | Transmission Noise Check  |
| Ok                         | Universal Joint Condition |
| Manual, electrical control | Transfer Gear Type        |

## Hydraulic System

|                               |                              |
|-------------------------------|------------------------------|
| Minor leak from control valve | Hydraulic Leaks              |
| Ok                            | Lift and Tilt Hydraulic Jack |
| Ok                            | Steering Hydraulic Jacks     |
| Functional                    | Hydraulic Pumps and Valves   |
| Ok                            | Swing Cylinders              |
| Ok                            | Boom Cylinder                |
| Ok                            | Stick Cylinder               |
| Ok                            | Bucket Cylinder              |
| N/A                           | Clamshell Cylinder           |

## Limited Functional Testing & Operation

|                              |                             |
|------------------------------|-----------------------------|
| Functional                   | Steering Function Test      |
| Functional                   | Transmission Operation Test |
| Functional                   | Loader Stall Test           |
| Functional                   | Braking System Test         |
| Ok                           | Pins Boom                   |
| Minor welding right jack pin | Pins Stick / Extension      |
| Ok                           | Rear Bucket Linkage         |
| Ok                           | Loader Pins & Hinges        |
| Ok                           | Outriggers & Pads           |
| N/A                          | Boom Side Tilt              |

## % Attachments Estimated Remaining Life

|                      |              |
|----------------------|--------------|
| -                    | Front Bucket |
| H900, W2300, D550 mm | Size         |
| Ok                   | Condition    |
| -                    | Rear Bucket  |
| H700, W700, D450 mm  | Size         |
| Ok                   | Condition    |



# PLANT & EQUIPMENT

Ok

Attachment Coupler

## % Tires Estimated Remaining Life

|                            |                                |
|----------------------------|--------------------------------|
| -                          | Front Right                    |
| Ozka 12.5/80-18 Tube Type  | Tire Brand & Size Details      |
| 50%                        | Tire Remaining Life Percentage |
| Ok                         | Tire Condition Notes           |
| -                          | Front Left                     |
| Ozka 12.5/80-18 Tube Type  | Tire Brand & Size Details      |
| 70%                        | Tire Remaining Life Percentage |
| Ok                         | Tire Condition Notes           |
| -                          | Rear Right                     |
| Farm boy 16.9-28 Tube Type | Tire Brand & Size Details      |
| 70%                        | Tire Remaining Life Percentage |
| Ok                         | Tire Condition Notes           |
| -                          | Rear Left                      |
| Ozka 16.5-28 Tube Type     | Tire Brand & Size Details      |
| 70%                        | Tire Remaining Life Percentage |
| Ok                         | Tire Condition Notes           |

## Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م  
دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة  
هاتف: +97148861125  
[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)