

## تقرير الفحص – 2018 هيتاشي ZX470H

الرقم التسلسلي: THEJAHL0T00000262 | ساعات: ١١١٧٧ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٧٤

### Key Features & Condition

|     |                                     |
|-----|-------------------------------------|
| N/A | Safety Certification Label          |
| N/A | Boom Hydraulic Check Valve          |
| N/A | Adjustable Boom System              |
| N/A | Automatic Lubrication System        |
| N/A | Arm Hydraulic Check Valve           |
| N/A | Diesel Particulate Filter           |
| N/A | Hydraulic Hammer Lines              |
| N/A | Grapple and Shear Hydraulic Lines   |
| N/A | Diesel Exhaust Fluid System AddBlue |
| N/A | Stabilizer Blade Condition          |
| Yes | Horn                                |

### Operator Cabin Details

|                                          |                                   |
|------------------------------------------|-----------------------------------|
| Ok                                       | Seat and Arm Support              |
| Ok                                       | Cab Doors & covers                |
| Ok                                       | Control Levers, Control Stick     |
| Left window broken, right mirror missing | Windows and Mirrors               |
| Ok                                       | Dashboard Screen, Gauges          |
| Ok                                       | Warning alarms message            |
| Not functional                           | Washer, Wipers                    |
| Not cooling                              | Air Conditioning & Heating System |
| Ok                                       | Cab Floor Covering                |
| Ok                                       | Cab Structure, Gard               |
| Need service                             | Electrical System                 |

### Engine & Performance

|                    |                       |
|--------------------|-----------------------|
| Mechanical         | Fuel Injection System |
| Isuzu - AA-6WG1TQA | Engine Model          |



|        |                          |
|--------|--------------------------|
| Ok     | Engine Cooling System    |
| Ok     | Engine Oil Check         |
| Ok     | Cooling System           |
| Ok     | Coolant                  |
| Ok     | Exhaust System & Muffler |
| Ok     | Belts & Air/Oil Filters  |
| Normal | Smoke Check              |
| Normal | Blowby                   |
| Ok     | Leaks & Seals            |

## Exterior Condition & Visual Inspection

|                           |                             |
|---------------------------|-----------------------------|
| Ok                        | Main Frame & Track Frame    |
| Ok                        | Protective Covers & Sheets  |
| Ok                        | Engine Hood                 |
| Ok                        | Side Access Doors           |
| Ok                        | Steps and Handrails         |
| Ok                        | Boom Condition              |
| Ok                        | Bumpers & Catwalk Condition |
| Ok                        | Arm Condition               |
| Ok, 2 lights need service | Lights                      |
| Ok                        | Battery Check               |
| Ok                        | Cabin Compartments          |
| Ok                        | Exterior Paint Condition    |

## Hydraulic System

|                          |                              |
|--------------------------|------------------------------|
| Slewing drive minor leak | Hydraulic Leaks              |
| Ok                       | Boom Hydraulic Jack          |
| Ok                       | Hydraulic Pump & Valve Block |
| Ok                       | Bucket Hydraulic Jack        |
| Ok                       | Arm Hydraulic Jack           |

## Performance analysis

|            |                            |
|------------|----------------------------|
| Ok         | Boom Pins Condition        |
| Functional | Excavator self- Drift Test |



|                |                                     |
|----------------|-------------------------------------|
| Ok             | Arm Pins Condition                  |
| Ok             | Hydraulic Pump Noise Check          |
| Ok,minor loose | Bucket Pins Condition               |
| Minor loose    | Slewing Ring Bearing Movement Check |
| Ok             | Swing Drive and Brake Test          |
| Ok             | Drive force Test                    |

## Attachments

|                           |                          |
|---------------------------|--------------------------|
| Bucket                    | Attachments model        |
| W 1770, H 1550, D 1200 mm | Size                     |
| Ok                        | Status                   |
| Ok                        | Coupler status           |
| N/A                       | Second Attachments model |
| N/A                       | Size                     |
| N/A                       | Status                   |

## Undercarriage

|              |                    |
|--------------|--------------------|
| Need service | bushings           |
| 70%          | Track shoes        |
| 50%          | idlers             |
| 600          | :shoe width in mm  |
| 80           | :track pitch in mm |
| 50%          | carrier rollers    |
| 50%          | Track rollers      |
| 60%          | Track links        |
| 70%          | Sprocket segments  |

## Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

