

تقرير الفحص – 2018 جيه سي بي 380LC

الرقم التسلسلي: PUNJD38CCJ2500802 | ساعات: ١٧١٧٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٠٣٦

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
Yes	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn
N/A	Rear Camera
N/A	E-Cataloge
N/A	Radio

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, front down glass has crack	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok, not functional	Washer, Wipers
Extenal, ok	Air Conditioning & Heating System
N/A	Cab Floor Covering
Ok	Cab Structure, Guard
Need service	Electrical System



Engine & Performance

Electronic, need service
JCB DIESELMAX 672 TCAE Electronic
Engine.
Ok
Ok
Ok,normal water
Ok
Ok
Normal
Normal
Ok

Fuel Injection System
Engine Model
Engine Cooling System
Engine Oil Check
Coolant
Exhaust System & Muffler
Belts & Air/Oil Filters
Smoke Check
Blowby
Leaks & Seals

Exterior Condition & Visual Inspection

Ok, minor welding on boom lift jack base
Ok
Ok, lift support is missing
Ok
Ok
Ok
Ok
Minor crack, minor welding on bucket pin side
Ok, boom light is missing, need 2 bulbs
Ok
Ok, fuse cover is missing
Ok, some parts repainted

Main Frame & Track Frame
Protective Covers & Sheets
Engine Hood
Side Access Doors
Steps and Handrails
Boom Condition
Bumpers & Catwalk Condition
Arm Condition
Lights
Battery Check
Cabin Compartments
Exterior Paint Condition

Hydraulic System

Ok, minor
Ok
Ok
Ok
Ok

Hydraulic Leaks
Boom Hydraulic Jack
Hydraulic Pump & Valve Block
Bucket Hydraulic Jack
Arm Hydraulic Jack



Performance analysis

Ok, lift cylinder pin minor loose	Boom Pins Condition
Ok	Excavator self- Drift Test
Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok, swing drive oil level is high	Swing Drive and Brake Test
Ok, right is little weaker	Drive force Test

Attachments

Bucket	Attachments model
W1550, H1300, D115 mm	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

50%	Bushings
60%	Track Shoes
R70%, L50%	Idlers
600	:Shoe Width In Mm
80	:Track Pitch In Mm
60%	Carrier Rollers
60%	Track Rollers
60%	Track Links
70%	Sprocket Segments

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

