

تقرير الفحص – 2018 ماسي فيرغسون MF7720

الرقم التسلسلي: VKKMX65EVJB108015 | ساعات: ٣٢٠٨ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١٠١٢

Key Features & Condition

N/A	Safety Certification Label
N/A	Environmental Protection Agency
N/A	A/C
Yes	PTO
Yes	4WED
N/A	All Wheel Steer
Yes	Point Linkage-3
Yes	Drawbar
N/A	Emission Compliance Label
N/A	Horn Function
Yes	Closed Cabin
Yes	CE Specification
Yes	Shift Speed Controller
Yes	Front Axle Suspension
Yes	Cabin Suspension
Yes	Engine Speed Memory Control
Yes	DEF
Yes	Spool valve
Yes	Crous control

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok, main control lever is broken	Controls, Levers
Ok, left side glass broken, front left mirror missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Service light is on	Warning alarms message



Ok, rear not functional	Washer, Wipers
Not Functional	Air Condition & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure
Need Service	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
AGCO POWER 200 Hp (147 Kw)	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Need change	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Ok	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Chassis
Ok	Engine Hood
Ok	Steering Linkage
Ok	Access Steps and Handrails
Ok	Exterior Paint Condition
Ok, engine side sheets missing	Sheet Metal
Ok	Wheel Fenders
Not Functional	Lights Check
Need change	Battery Check
Ok	Rims, Wheel Nuts

Power Train Inspection

Ok	Axles and Differentials
Ok	Transmission Leak
Ok	Power Train force



Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- Auto 4 gear	Transfer Gear Type

Hydraulic System

Ok, minor	Hydraulic Leaks
Not tested	Remote Hydraulic Controls
Not tested	Steering Hydraulic Jacks
Not tested	Hydraulic Pumps and Valves
Not tested	(Cylinder(s)

Limited Functional Testing & Operation

Ok	Steering Function Test
Ok	Transmission Operation Test
Not tested	Cylinder Pins and Bushings
Ok	Braking System Test
Not tested	Spool Valve Electronic/ Manual

% Tires Estimated Remaining Life

-	Front Right
RUNGOD 18.4- 30	Tire Brand & Size Details
40%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
-	Front Left
BKT 18.4- 30	Tire Brand & Size Details
90%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
-	Rear Right
Galaxy 650/65R42	Tire Brand & Size Details
80%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
-	Rear Left
Galaxy 650/65R42	Tire Brand & Size Details
90%	Tire Remaining Life Percentage



يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

