

تقرير الفحص – 2023 اكس سي ام جي XCT80

الرقم التسلسلي: LXGCPA508PA003739 | كم: ٧٤٠٨ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٨٥٤

Key Features & Condition

N/A	CE Labeling
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Extended Fuel tank
N/A	Retarder
N/A	Rear Axle Lifter
Yes	Axle Steering 2

Truck Cab

Ok	Driver Seat
Ok	Switches, Levers
Gauges functional, screen is not functional	Gauges, Warn Lights
Not cooling	Aircon / Heater
Ok	Passenger Seat
Ok	Cab Doors
Ok, right small mirror cracked	Windows, Mirrors
Ok	Wipers, Washers
Ok	Interior, Covers
Ok	Radio

Crane operator cab

Ok	Driver Seat
Ok	Switches, Levers
Ok	Gauges, Warn Lights
N/A	Aircon / Heater



Ok	Cab Doors
Ok	Windows
Ok	Wipers
Ok	Interior Covers

Engine

Electronic	Injection Type
wp12.375e50	Engine Model
Ok	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler
Ok	Cooling System
Normal	Smoke, Fume
Normal	Blow By
Ok	Belts, Pulleys
Ok, normal water	Coolant Condition

Visual inspection exterior

Ok, minor welding	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok, repainted	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Ok	Lights

Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
Wear-Out	Rubber Sleeves
Ok	Brake Pads/Disks
Functional	Compressor
Manual, need minor service	Transfer Gear
Ok	Universal Joints



Functional
Need service

Transmission
Clutch

Hydraulics / Steering

Ok
Ok
Ok
Ok
Ok

Hoses & Lines
Hydraulic Pump
PTO
Steering Cylinders
Steering Linkage

Carrier Limited Functional Test

Functional hard gear shift
Functional hard gear shift
N/A
Functional
Functional
Functional
Not tested

Transmission Forward
Transmission Reverse
Automatic Group Select
Service Brake
Park Brake
Electrics
Retarder

Crane Condition / Limited Test

Functional
Ok
Ok
Ok
Functional
Ok
Not functional
Ok
Functional

Controls, Levers
Boom Conditions
Telescopic Segments
Hydraulic Cylinders
Swing Bearing / Drive
Hose Lines
Lift Limitations
Hook
Outriggers

% Tires Condition

-
60%
50%

Right
Axle 1
Axle 2 Inside



70% (2019 Need change)	Axle 3 Outside
70% (2019 Need change)	Axle 3 Inside
60% (2019 Need change)	Axle 4 Outside
60% (2019 Need change)	Axle 4 Inside
-	Left
60%	Axle 1
50%	Axle 2 Inside
60% (2019 Need change)	Axle 3 Outside
60% (2019 Need change)	Axle 3 Inside
60% (2019 Need change)	Axle 4 Outside
40% (2019 Need change)	Axle 4 Inside

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

