

تقرير الفحص – 2018 كاتربيلر 336D2

الرقم التسلسلي: CAT0336DHFAJ12344 | ساعات: ٧١٣٠ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ٧٢٧

Key Features & Condition

| | |
|-----|-------------------------------------|
| N/A | Safety Certification Label |
| N/A | Boom Hydraulic Check Valve |
| N/A | Adjustable Boom System |
| N/A | Automatic Lubrication System |
| N/A | Arm Hydraulic Check Valve |
| N/A | Diesel Particulate Filter |
| Yes | Hydraulic Hammer Lines |
| N/A | Grapple And Shear Hydraulic Lines |
| N/A | Diesel Exhaust Fluid System Addblue |
| N/A | Stabilizer Blade Condition |
| N/A | Horn |

Operator Cabin Details

| | |
|-----------------------------|-----------------------------------|
| Ok | Seat And Arm Support |
| Ok | Cab Doors & Covers |
| Ok | Control Levers, Control Stick |
| Ok, Right Mirror Is Missing | Windows And Mirrors |
| Ok | Dashboard Screen, Gauges |
| Ok | Warning Alarms Message |
| Ok | Washer, Wipers |
| Ok | Air Conditioning & Heating System |
| Ok | Cab Floor Covering |
| Ok | Cab Structure, Gard |
| Ok | Electrical System |

Engine & Performance

| | |
|------------|-----------------------|
| Electronic | Fuel Injection System |
| C9 Engine | Engine Model |



| | |
|------------------|--------------------------|
| Ok | Engine Cooling System |
| Ok | Engine Oil Check |
| Ok | Cooling System |
| Ok, Normal Water | Coolant |
| Ok | Exhaust System & Muffler |
| Ok | Belts & Air/Oil Filters |
| Normal | Smoke Check |
| Normal | Blowby |
| Ok | Leaks & Seals |

Exterior Condition & Visual Inspection

| | |
|-----------------|-----------------------------|
| Ok | Main Frame & Track Frame |
| Ok | Protective Covers & Sheets |
| Ok | Engine Hood |
| Ok, Minor Dents | Side Access Doors |
| Ok, Minor Dents | Steps And Handrails |
| Ok | Boom Condition |
| Ok | Bumpers & Catwalk Condition |
| Ok | Arm Condition |
| Ok | Lights |
| Ok | Battery Check |
| Ok | Cabin Compartments |
| Ok | Exterior Paint Condition |

Hydraulic System

| | |
|--------------------|------------------------------|
| Ok | Hydraulic Leaks |
| Ok, Minor Oil Leak | Boom Hydraulic Jack |
| Ok | Hydraulic Pump & Valve Block |
| Ok, Minor Oil Leak | Bucket Hydraulic Jack |
| Ok | Arm Hydraulic Jack |

Performance Analysis

| | |
|----|----------------------------|
| Ok | Boom Pins Condition |
| Ok | Excavator Self- Drift Test |



| | |
|-----------------|-------------------------------------|
| Ok | Arm Pins Condition |
| Ok | Hydraulic Pump Noise Check |
| Ok. Minor Loose | Bucket Pins Condition |
| Ok | Slewing Ring Bearing Movement Check |
| Ok | Swing Drive And Brake Test |
| Ok | Drive Force Test |

Attachments

| | |
|----------------------|--------------------------|
| Bucket | Attachments Model |
| W1340 H1300 D1000 Mm | Size |
| Ok | Status |
| Ok | Coupler Status |
| N/A | Second Attachments Model |
| N/A | Size |
| N/A | Status |

Undercarriage

| | |
|--------|--------------------|
| 60% | Bushings |
| 80% | Track Shoes |
| 60% | Idlers |
| Mm 600 | :Shoe Width In Mm |
| Mm 140 | :Track Pitch In Mm |
| 70% | Carrier Rollers |
| 60% | Track Rollers |
| 60% | Track Links |
| 60% | Sprocket Segments |

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

