

Inspection report – 2011 Caterpillar D7G

Serial No: CAT00D7GV7MB05612 | Hours: 10511 | Location: Dubai, United Arab Emirates | SKU: 1082

Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	N/A
Ripper Control Valve	N/A
Low Ground Pressure Tracks	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	N/A
Controls, Levers	Ok
Windows and Mirrors	N/A
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Gard	N/A
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	3306
Engine Cooling System	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Push Frame & Trunnions	Ok
Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Ok
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Ok, need 4 bulbs
Push Arm Pivot Shaft	N/A
Tilt Linkage Pins & Bushings	N/A

Hydraulic System

Hydraulic Leaks	Ok
Lift Hydraulic Jacks	Ok
Ripper Lift Hydraulic Jacks	N/A
Tilt Hydraulic Jack	N/A
Angle Hydraulic Jack	N/A
Ripper Angle Hydraulic Jacks	N/A

Limited Functional Testing & Operation

Push Frame Pins	Ok
Blade Pins	Ok
Ripper Pins	N/A
Equalizer Bar Condition	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Bulldozer Stall Test	Ok
Steering Function Test	Ok
Blade Tilt and Lift Test	Ok, no tilt
Undercarriage Pivot Pins	N/A
Transmission Test	Ok
Brake System Test	Ok
Torque Converter Test	Ok

Blade Inspection

Blade Base Condition	Ok
Spill Rack Condition	Ok
Blade Front Condition	Ok
Blade Edge Condition	Ok

Undercarriage Inspection

Right Side Undercarriage Wear

Undercarriage Bushings	80%
Undercarriage Shoes	80%
Front Idler Condition	80%
Rear Idler Condition	N/A
Carrier Roller Condition	80%
Track Links Condition	80%
Sprocket Condition	80%
Roller Condition	80%
Track Canon Condition	N/A

Left Side Undercarriage Wear

Undercarriage Bushings	80%
Undercarriage Shoes	80%
Front Idler Condition	80%
Rear Idler Condition	N/A
Carrier Roller Condition	80%
Track Links Condition	80%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Sprocket Condition	80%
Roller Condition	80%
Track Canon Condition	N/A
Track Width Measurement	W610,L250 mm

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

