

## Inspection report – 2011 Caterpillar D7G

Serial No: CAT00D7GV7MB05612 | Hours: 10511 | Location: Dubai, United Arab Emirates | SKU: 990

---

### Key Features & Condition

|                            |     |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Ground Ripper              | N/A |
| Ripper Control Valve       | N/A |
| Low Ground Pressure Tracks | N/A |
| Operator's Manual          | N/A |
| Emission Compliance Label  | N/A |
| Grade Control System       | N/A |
| Equipment Parts Manual     | N/A |
| CAT System One             | N/A |
| Horn                       | Yes |

---

### Operator Cabin Details

|                                   |     |
|-----------------------------------|-----|
| Seat and Arm Support              | Ok  |
| Cab Doors & covers                | N/A |
| Controls, Levers                  | Ok  |
| Windows and Mirrors               | N/A |
| Dashboard Screen, Gauges          | Ok  |
| Warning alarms message            | Ok  |
| Washer, Wipers                    | N/A |
| Air Conditioning & Heating System | N/A |
| Cab Floor Covering                | N/A |
| Cab Structure, Gard               | N/A |
| Electrical System                 | Ok  |

---

### Engine & Performance

|                       |            |
|-----------------------|------------|
| Fuel Injection Type   | Mechanical |
| Engine Model          | 3306       |
| Engine Cooling System | Ok         |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |        |
|--------------------------|--------|
| Engine Oil Check         | Ok     |
| Blowby                   | Normal |
| Exhaust System & Muffler | Ok     |
| Belts & Air/Oil Filters  | Ok     |
| Smoke                    | Normal |
| Coolant                  | Ok     |
| Fluid Leaks              | Ok     |

---

## Exterior Condition & Visual Inspection

|                                   |                  |
|-----------------------------------|------------------|
| Push Frame & Trunnions            | Ok               |
| Doors, Covers, and Grilles        | Ok               |
| Access Steps & Handrails          | Ok               |
| Exterior Paint Condition          | Ok               |
| Blade Trunnions & Bushings        | Ok               |
| Underbody Protection Plates       | Ok               |
| Final Drive Condition             | Ok               |
| Fuel Tank, Roof, & Hood Condition | Ok               |
| Lights and Battery Check          | Ok, need 4 bulbs |
| Push Arm Pivot Shaft              | N/A              |
| Tilt Linkage Pins & Bushings      | N/A              |

---

## Hydraulic System

|                              |     |
|------------------------------|-----|
| Hydraulic Leaks              | Ok  |
| Lift Hydraulic Jacks         | Ok  |
| Ripper Lift Hydraulic Jacks  | N/A |
| Tilt Hydraulic Jack          | N/A |
| Angle Hydraulic Jack         | N/A |
| Ripper Angle Hydraulic Jacks | N/A |

---

## Limited Functional Testing & Operation

|                         |     |
|-------------------------|-----|
| Push Frame Pins         | Ok  |
| Blade Pins              | Ok  |
| Ripper Pins             | N/A |
| Equalizer Bar Condition | N/A |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |             |
|--------------------------|-------------|
| Bulldozer Stall Test     | Ok          |
| Steering Function Test   | Ok          |
| Blade Tilt and Lift Test | Ok, no tilt |
| Undercarriage Pivot Pins | N/A         |
| Transmission Test        | Ok          |
| Brake System Test        | Ok          |
| Torque Converter Test    | Ok          |

---

## Blade Inspection

|                       |    |
|-----------------------|----|
| Blade Base Condition  | Ok |
| Spill Rack Condition  | Ok |
| Blade Front Condition | Ok |
| Blade Edge Condition  | Ok |

---

## Undercarriage Inspection

---

### Right Side Undercarriage Wear

|                          |     |
|--------------------------|-----|
| Undercarriage Bushings   | 80% |
| Undercarriage Shoes      | 80% |
| Front Idler Condition    | 80% |
| Rear Idler Condition     | N/A |
| Carrier Roller Condition | 80% |
| Track Links Condition    | 80% |
| Sprocket Condition       | 80% |
| Roller Condition         | 80% |
| Track Canon Condition    | N/A |

---

### Left Side Undercarriage Wear

|                          |     |
|--------------------------|-----|
| Undercarriage Bushings   | 80% |
| Undercarriage Shoes      | 80% |
| Front Idler Condition    | 80% |
| Rear Idler Condition     | N/A |
| Carrier Roller Condition | 80% |
| Track Links Condition    | 80% |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                         |              |
|-------------------------|--------------|
| Sprocket Condition      | 80%          |
| Roller Condition        | 80%          |
| Track Canon Condition   | N/A          |
| Track Width Measurement | W610,L250 mm |

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

