

## Inspection report – 2011 Massey Ferguson 6480

Serial No: B160017 | Hours: 4068 | Location: Dubai, United Arab Emirates | SKU: 1011

---

### Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	N/A
PTO	Yes
4WED	Yes
All Wheel Steer	N/A
3-Point Linkage	Yes
Drawbar	Yes
Emission Compliance Label	N/A
Horn Function	N/A
Closed Cabin	Yes
CE Specification	Yes
Shift Speed Controller	Yes
Front Axle Suspension	N/A
Cabin Suspension	Yes
Engine Speed Memory Control	Yes

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok, left door glass broken and lock need repair
Controls, Levers	Ok
Windows and Mirrors	Ok, front left mirror missing
Dashboard Screen, Gauges	Ok, monitor not functional
Warning alarms message	Error E9151, E9023, air flow sensor, oil pressur, oil temperture
Washer, Wipers	Ok, rear not functional
Air Condition & Heating System	Not functional
Cab Floor Covering	Ok
Cab Structure	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Electrical System

Need service

---

## Engine & Performance

Fuel Injection Type	Electronic
Engine Model	SisuDiesel / 6 cyl.Turbo/intercooled
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, filters need change
Smoke	Normal
Coolant	Normal water
Fluid Leaks	Minor oil leak from turbo gasket, minor diesel leak from first injector feed pipe

---

## Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Steering Linkage	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Sheet Metal	N/A
Wheel Fenders	Ok, front right missing
Lights Check	Not functional, 1 missing
Battery Check	Ok
Rims, Wheel Nuts	Ok

---

## Power Train Inspection

Axles and Differentials	Ok
Transmission Leak	Ok
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi-Auto 4 gear

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Hydraulic System

Hydraulic Leaks	Ok
Remote Hydraulic Controls	Available, not tested
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok
Cylinder(s)	N/A

## Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Cylinder Pins and Bushings	N/A
Braking System Test	Ok

## Tires Estimated Remaining Life %

Front Right	-
Tire Brand & Size Details	ASCENSO 16,9-28
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new
Front Left	-
Tire Brand & Size Details	ASCENSO 16,9-28
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new
Rear Right	-
Tire Brand & Size Details	ASCENSO 600/ 65R38
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new
Rear Left	-
Tire Brand & Size Details	ASCENSO 600/ 65R38
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new

## Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



warranties or guarantees expressed or implied.

---

**Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.**

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

