

Inspection report – 2012 Liebherr LTM 1070-4.2

Serial No: W09484600CEL05368 | Hours: 13672 | Location: Dubai, United Arab Emirates | SKU: 1013

Key Features & Condition

CE Labeling	Yes
Automatic Shift	Yes
Semi-Automatic	N/A
Tachograph	Yes
Auto Lube	N/A
A/C	Not functional
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	Yes
2 Axle Steering	Yes
Cruise Control	Yes
Air Suspension	Yes
Bluetooth Controller	Yes

Truck Cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Ok
Aircon / Heater	Not cooling
Passenger Seat	Ok
Cab Doors	Ok
Windows, Mirrors	Ok
Wipers, Washers	Ok
Interior, Covers	Ok
Radio	Ok

Crane operator cab

Driver Seat	Ok
-------------	----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Switches, Levers	Ok
Gauges, Warn Lights	Ok,hard visual minor sunburnt
Aircon / Heater	Not cooling
Cab Doors	Ok
Windows	Ok
Wipers	Ok
Interior Covers	Ok

Engine

Injection Type	Electrical
Engine Model	LTM 1070-4.2
Leaks, Seals	Ok
Oil Condition	Ok
Exhaust/Muffler	Ok
Cooling System	Ok
Smoke, Fume	Ok
Blow By	Normal
Belts, Pulleys	Ok
Coolant Condition	Ok

Visual inspection exterior

Chassis, Frames	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok
Lights	Ok
Batteries	Ok
Main Hook	Ok

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Ok, Automatic
Clutch	N/A

Hydraulics / Steering

Hoses & Lines	Ok
Hydraulic Pump	Ok
PTO	Ok
Steering Cylinders	Ok
Steering Linkage	Ok
Lift Limitation	Ok
Outriggers	Ok
Hook	Ok
Boom Cylinder	Ok

Carrier Limited Functional Test

Transmission Forward	Ok
Transmission Reverse	Ok
Automatic Group Select	Ok
Service Brake	Ok
Park Brake	Ok
Electrics	Ok
Retarder	Ok

Crane Condition / Limited Test

Drive Forward & Back Function	Ok
Controls, Levers Function	Ok
Boom Conditions	Ok
Telescopic Segments Function	Ok
Hydraulic Cylinders Function	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Swing Bearing / Drive Function	Ok
Hose Lines	Ok
Lift Limitations Function	Ok
Hook	Ok
Outriggers Function	Ok
Automatic Outrigger Leveling	Need service

Tires Condition %

Right	-
Axle 1	70% Airomax
Axle 2	70% Goodride
Axle 3	70% Goodride
Axle 4	70% Goodride
Left	-
Axle 1	70% Goodride
Axle 2	70% Airomax
Axle 3	70% Goodride
Axle 4	70% Airomax
Tire Size	445/95R25

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

