

Inspection report – 2013 Caterpillar 226B3

Serial No: CAT0226BESNA00162 | Hours: 22873 | Location: Dubai, United Arab Emirates | SKU: 1030

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Emission Compliance Label	N/A
Closed Cabin	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok, need upholstery
Cab Doors & covers	Ok
Control Levers, Control Stick	Functional, minor leak
Windows and Mirrors	Only rear window, right mirror, and center mirror cracked, left mirror handle not original.
Gauges	Fuel gauge need replace
Warning alarms message	N/A
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	Ok
Cab Structure, Guard	Ok
Electrical System	Ok
Start key	Ok
Main Safety Switch	Ok
Engine rpm Throttle Lever	Not functional

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	C2.2 Serial nom: CYS21623
Engine Cooling System	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Ok
Blowby	Minor
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Normal water
Leaks& seals	Minor Gasket leak

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Protective Covers & Sheets	Ok
Engine Door	Ok, no Lock
Lights	Ok
Battery Check	Ok
Exterior Paint Condition	Repainted

Hydraulic System

Hydraulic Leaks	Minor leaks
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital (drive motor)	Ok
Hydraulic Pumps and Valves	Functional

Limited Functional Testing & Operation

Drive Function Test	Functional
Skid steer Stall Test	Functional
Brake System Test	Functional
Attachment Pins	Minor Loose
Final Drive Motors Test	Functional
Park Break	Functional

Attachments

Attachments model	Bucket
Size	W1530, H700, D400 mm

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Bottom condition	Ok
Edge & teeth condition	Ok, no teeth
Bucket side condition	Ok
Coupler status	Ok

Tires Estimated Remaining Life %

Front Right	40%
Front Left	40%
Rear Right	40%
Rear Left	40%
Size	10-16.5
Type	Tube less
wheel Rims & Nuts	Ok, 1 nut missing

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

