

## Inspection report – 2013 Volvo L105

Serial No: VCE0L105C00001073 | Hours: 15275 | Location: Dubai, United Arab Emirates | SKU: 1023

---

### Key Features & Condition

|                                      |     |
|--------------------------------------|-----|
| Safety Certification Label           | N/A |
| Automatic Lubrication System         | N/A |
| Auxiliary Hydraulic Valve            | N/A |
| Equipment Parts Manual               | N/A |
| Air Conditioning System              | N/A |
| Hydrostatic Drive System (Hydrostat) | N/A |
| Supplemental Steering System         | N/A |
| Operator's Manual                    | N/A |
| Emission Compliance Label            | N/A |
| Quick Attachment Coupler             | N/A |
| Load Weighing System                 | N/A |
| Horn Function                        | N/A |

---

### Operator Cabin Details

|                                   |  |
|-----------------------------------|--|
| Seat and Arm Support              | Ok   |
| Cab Doors & covers                | Ok   |
| Controls, Levers                  | Ok   |
| Windows and Mirrors               | Ok, left mirror broken                     |
| Dashboard Screen, Gauges          | Ok   |
| Warning alarms message            | Park break failure/ reduced shift function |
| Washer, Wipers                    | Ok   |
| Air Conditioning & Heating System | Not cooling                                |
| Cab Floor Covering                | Ok, not original                           |
| Cab Structure, Gard               | Ok   |
| Electrical System                 | Ok   |

---

### Engine & Performance

|                     |            |
|---------------------|------------|
| Fuel Injection Type | Electronic |
|---------------------|------------|

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |           |
|--------------------------|-----------|
| Engine Model             | Volvo D7D |
| Engine Cooling System    | Ok        |
| Engine Oil Check         | Ok        |
| Blowby                   | Normal    |
| Exhaust System & Muffler | Ok        |
| Belts & Air/Oil Filters  | Ok        |
| Smoke                    | Normal    |
| Coolant                  | Ok        |
| Fluid Leaks              | Ok        |

---

## Exterior Condition & Visual Inspection

|                            |                         |
|----------------------------|-------------------------|
| Main Frame and Lift Arm    | Ok                      |
| Engine Hood                | Ok                      |
| Access Steps and Handrails | Ok                      |
| Exterior Paint Condition   | Ok, repainted           |
| Counterweight Condition    | Ok                      |
| Wheel Fenders              | Ok                      |
| Lights Check               | 2- Ok, 4 not functional |
| Battery Check              | Ok                      |

---

## Power Train Inspection

|                           |                       |
|---------------------------|-----------------------|
| Axles and Differentials   | Ok                    |
| Transmission Gearbox      | Ok                    |
| Power Train force         | weak du to park break |
| Transmission Noise Check  | Ok                    |
| Universal Joint Condition | Ok                    |
| Transfer Gear Type        | Semi- auto            |

---

## Hydraulic System

|                              |    |
|------------------------------|----|
| Hydraulic Leaks              | Ok |
| Lift and Tilt Hydraulic Jack | Ok |
| Steering Hydraulic Orbital   | Ok |
| Steering Hydraulic Jacks     | Ok |
| Hydraulic Pumps and Valves   | Ok |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Limited Functional Testing & Operation

|                             |    |
|-----------------------------|----|
| Steering Function Test      | Ok |
| Transmission Operation Test | Ok |
| Loader Stall Test           | Ok |
| Brake System Test           | Ok |
| Articulation Movement Check | Ok |
| Loader Attachment Pins      | Ok |

---

## Attachments

|                               |                       |
|-------------------------------|-----------------------|
| Bucket Width and Capacity     | W1350, h1250, d950 mm |
| Bucket Bottom Condition       | Ok                    |
| Bucket Edge & Teeth Condition | Ok                    |
| Bucket Side Condition         | Ok                    |
| Attachment Coupler            | Ok                    |

---

## Tires Inspection

|                                |                   |
|--------------------------------|-------------------|
| Front Right                    | -                 |
| Tire Brand & Size Details      | China 23.5-25     |
| Tire Remaining Life Percentage | 100%              |
| Tire Condition Notes           | New, tube type    |
| Wheel Rims & Nuts              | Ok                |
| Front Left                     | -                 |
| Tire Brand & Size Details      | China 23.5-25     |
| Tire Remaining Life Percentage | 100%              |
| Tire Condition Notes           | New, tube type    |
| Wheel Rims & Nuts              | Ok                |
| Rear Right                     | -                 |
| Tire Brand & Size Details      | Green 23.5-25     |
| Tire Remaining Life Percentage | 100%              |
| Tire Condition Notes           | New, tube type    |
| Wheel Rims & Nuts              | Ok                |
| Rear Left                      | -                 |
| Tire Brand & Size Details      | Gann shan 23.5-25 |
| Tire Remaining Life Percentage | 100%              |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Tire Condition Notes

New, tube type

Wheel Rims & Nuts

Ok

---

## Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

