

PLANT & EQUIPMENT

Inspection report – 2014 TATA Daewoo M9AVF

Serial No: KL3M9AVF1EK000616 | Km: 176092 | Location: Dubai, United Arab Emirates | SKU: 1113

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	Manual
Semi-Automatic	Manual
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	N/A
Hill stand aid function	Yes
Horn off-on	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	Not working
Navigation	N/A
ABS	Yes
Driver bed	Yes
Moving off aid	Yes
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes, not tested
Rear Axle Lifter	N/A
Radio	N/A
TRC	N/A
Camera sensor	N/A
Differential lock	Yes
Advanced emergency brake assist	Yes
Water Tank	Yes

Truck Cabin Details

Seat and Arm Support	Need upholstery
----------------------	-----------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Cab Doors & covers	Ok, need minor service, no covers , passenger door doesn't close
Controls, Levers	Ok
Windows and Mirrors	Front glass broken, windows control need service
Dashboard Screen, Gauges	Not Functional only water temperature
Warning alarms message	Not functional
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Need minor service
Interior, Covers	Ok
Passenger Seat	Need upholstery
Radio	N/A

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	DV15TIS
Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Blowby	Normal
Exhaust System & Muffler	Minor welding
Belts & Air/Oil Filters	Need change
Smoke	Normal
Coolant	Normal water
Fluid Leaks	Oil sump leaks, minor leak from gasket and turbo oil pressure
Starting	Start directly from the starter and shut down from the pump throttle

Exterior Condition & Visual Inspection

Chassis, Frames	Ok, minor rust
Frame Stamp Serial Number	Ok
Sheet Metal, Covers	Ok, minor rust
Steps, Grab Irons	Ok, minor dent

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Paintwork	Ok
Cooler Grill	Ok
Bumpers	Front bumper need change broken
Lights / Batteries	Drive light broken, need 6 bulbs, batteries need change
Fenders	Ok
Suspension Springs/Hangers	spring leaf minor loose
Suspension Bushings	4 rear bushings worn out
Water Tank	Ok

Power Train

Axels/Differentials	Ok, diffrentials minor leak
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Need service
Compressor	Major leak
Transfer Gear	Ok
Universal Joints	Minor loose
Transmission	Manual, need minor electric service
Clutch	Functional

Truck Limited Functional Test

Transmission Forward	Functional
Transmission Reverse	Functional
Steering	Functional
Automatic Group Select	N/A
Service Brake	2 Rear boosters need change
Park Brake	Ok
Electrics	Need minor service
Retarder	Not tested

hydraulics

PTO Pump	Not functional
Water pump	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

cabine lift cylinder & valve

Not functional,

Tires

Axle 1 / RHS (%) / LHS (%)	R70%, L70%
Axle 2 Inside / RHS (%) / LHS (%)	R70%, L70%
Axle 2 Outside / RHS (%) / LHS (%)	R70%, L70%
Axle 3 Inside / RHS (%) / LHS (%)	R50%, L60%
Axle 3 Outside / RHS (%) / LHS (%)	R40%, L70%
Axle 4 Inside / RHS (%) / LHS (%)	R30%, L40%
Axle 4 Outside / RHS (%) / LHS (%)	R30%, L30%
Tire Size	Axle1&2 315/80 R 22.5, Axle 3&4 12 R 22.5

Water Tank

size	7000L
condition	Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

