

PLANT & EQUIPMENT

Inspection report – 2014 TATA Daewoo M9AVF

Serial No: KL3M9AVF1EK000613 | Location: Dubai, United Arab Emirates | SKU: 1111

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	N/A
Hill stand aid function	Yes
Horn off-on	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Navigation	N/A
ABS	Yes
Driver bed	Yes
Moving off aid	N/A
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	N/A
Radio	N/A
TRC	N/A
Camera sensor	N/A
Differential lock	Yes
Advanced emergency brake assist	Yes
Water Tank	Yes

Truck Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Need service



PLANT & EQUIPMENT

Controls, Levers	Need service
Windows and Mirrors	2 mirrors glass broken, front glass cracked, driver blind spot window cracked
Dashboard Screen, Gauges	Not functional
Warning alarms message	Not functional
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Need service
Interior, Covers	Need service
Passenger Seat	Need upholstery
Radio	N/A
Electrical System	Need service, starts direct from starter, switch off from fuel bump switch

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	DV15TIS
Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Fluid Leaks	Minor from oil sump, side cover
Starting	Direct from starter

Exterior Condition & Visual Inspection

Chassis, Frames	Ok, minor rust
Frame Stamp Serial Number	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok, need service
Paintwork	Ok
Cooler Grill	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Bumpers

Lights / Batteries

Fenders

Suspension Springs/Hangers

Suspension Bushings

Water Tank

Front bumper need repair

Front signal light missing, need 4 bulbs

Ok

Front and rear springs minor loose

Front bushes need replace

Ok

Power Train

Axels/Differentials

Ok

Stabilizers, Beams

Spring leafs minor loose

Rubber Sleeves

N/A

Brake Pads/Disks

Ok

Compressor

Ok, minor leak

Transfer Gear

Ok

Universal Joints

Ok, minor loose

Transmission

Ok, manual

Clutch

Ok

Truck Limited Functional Test

Transmission Forward

Ok

Transmission Reverse

Ok

Steering

Ok

Automatic Group Select

N/A

Service Brake

Ok

Park Brake

Ok

Electrics

Need minor service

Retarder

Ok

hydraulics

PTO Pump

N/A

Water pump

Not tested

cabine lift cylinder & valve

Not functional, Jack leaks

Tires

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Axle 1 / RHS (%) / LHS (%)	R50%, L70%
Axle 2 / RHS (%) / LHS (%)	R10%, L50%
Axle 3 Inside / RHS (%) / LHS (%)	R40%, L no tire
Axle 3 Outside / RHS (%) / LHS (%)	R40%, L no tire
Axle 4 Inside / RHS (%) / LHS (%)	R70%, L 60%
Axle 4 Outside / RHS (%) / LHS (%)	R10%, L 40%
Tire Size	-

Water Tank

size	5000 gallon
condition	Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

