

Inspection report – 2015 Hyundai Sonata

Serial No: 5NPE34AF0FH057429 | Km: 298737 | Location: Dubai, United Arab Emirates | SKU: 989

Specifications and Standards

4WD	N/A
Draw Bar	N/A
Spare Tire	Yes
Spare Tire Tools	Yes
Xenon Head Lights	N/A
Gear Paddle Shifter	N/A
Rear camera	Yes
Air Condition	Yes
Cooling&Heating Seats	Heating only
Radio	Yes
Car Type	Sedan
4 Seats	Yes
Sport& Snow Modes	Sport & Eco
3 Steering Mode	N/A
Blind spot sensor	Yes
Tire presure sensor	Yes
LED Head Light	Yes
Keyless Entry	Yes

Interior

Seats	Ok
Switches	Ok
Gauges	Ok
Aircon / Heater	Ok
Ceiling	Ok
Cab Doors	Ok
Windows / mirror	Ok
Wipers	Ok
Floor Mates	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine

Model	2.4 GDI
Leaks	Ok
Oil Condition	Ok
Exhaust	Ok
Cooling System	Ok
Fuel Type	Petrol
Sound	Ok
Smoke	Normal
Blow By	Normal
Belts	AC belt need change
Power	Ok
Size & Horse Power	2.4L, 4cylinder, 185Hp

Exterior

Chassis	Ok
Roof	Ok
Under Engine Cover	Ok
Door Handles	Ok
Paintwork	Need polish
Cooler Grill	Ok
Bumpers	Ok
Petrol Tank Cover	Ok
Lights	Ok, left fog light not functional, left indicator not functional when head lights are on

Power Train

Axels	Ok
Gearbox	Ok
Transmission Gear	Ok
Transfer Gear	Ok, Automatic
Universal Joints	Ok
Differentials	Ok
Brake Drums/Disk	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Limited Functional Test

Drive Forward	Ok
Drive Reverse	Ok
Service Brake	Ok
Steering	Ok
Wheel Bearing	Ok
Suspensions	Ok, front left need checkup
Park Brake	Ok

Tires Axle 1

RHS mm (%) rem.	60%, Nexen
LHS mm (%)	70%, Tercelo
Cuts	Ok
Date	2024
Size	215/55R17

Tires Axle 2

RHS mm (%) rem.	80% Nexen
LHS mm (%)	60% Nexen
Cuts	Ok
Date	2024
Size	215/55R17

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

