

PLANT & EQUIPMENT

Inspection report – 2015 TOYOTA HILUX

Serial No: MR0FX22G8F1437986 | Km: 635019 | Location: Dubai, United Arab Emirates | SKU: 1124

Specifications and Standards

4WD	Yes
Draw Bar	N/A
Spare Tire	N/A
Spare Tire Tools	N/A
Xenon Head Lights	N/A
Gear Paddle Shifter	N/A
Rear camera	N/A
Air Condition	Not cooling
Cooling&Heating Seats	N/A
Radio	Yes
Car Type	Double cabin pickup
hill descent control	Yes
cruise control	N/A

Interior

Seats	driver seat need upholstery
Switches	Ok
Gauges	Ok
Aircon / Heater	Not cooling
Ceiling	Ok
Cab Doors	Ok
Windows	Ok
Wipers	Need replacment
Floor Mates	Ok
Glove Compartment	Broken

Engine

Model	2.7L 2TR-FE Engine
Leaks	minor leak from head gasker & steering pump

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Oil Condition	Ok
Exhaust	Ok
Cooling System	Ok
Fuel Type	Petrol
Sound	Ok
Smoke	Normal
Blow By	Normal
Belts	Ok, dry need change
Power	Ok
Coolant	Ok
Size & Horse Power	2.7 L

Exterior

Chassis	Ok, minor rust
Roof	Ok
Under Engine Cover	Ok
Door Handles	Ok
Paintwork	Ok, front and rear bumper need fix and paint
Cooler Grill	Missing
Bumpers	Front bumper broken
Fuel Tank Cover	Ok
Lights	2 need bulbs, rear right is broken, 3 need polish
Deck	Ok

Power Train

Axels	Ok
Gearbox	Ok
Transmission Gear	Ok
Universal Joints	Ok
Differentials	Ok
Gear Type	Automatic

Limited Functional Test

Drive Forward	Ok
---------------	----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Drive Reverse	Ok
Service Brake	Ok
Steering	Ok, minor leak from pump
Wheel Bearing	Ok
Suspensions	Ok, need to change bushing and arms
Park Brake	Ok

Tires Axle 1

RHS (%) rem.	20% need change
LHS (%) rem.	20% need change

Tires Axle 2

RHS (%) rem.	40% dry need change
LHS (%) rem.	40% dry need change

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

