

Inspection report – 2016 Doosan DX225LC-9C

Serial No: DXCCEBCAJG0020089 | Hours: 5679 | Location: Dubai, United Arab Emirates | SKU: 1079

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple And Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System Addblue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A

Operator Cabin Details

Seat And Arm Support	Ok
Cab Doors & Covers	Ok
Control Levers, Control Stick	Ok
Windows And Mirrors	Ok
Dashboard Screen, Gauges	Ok, Some Warn Lights Are Active
Warning Alarms Message	Ok
Washer, Wipers	Not Functional
Air Conditioning & Heating System	Not Functional
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Need Minor Service

Engine & Performance

Fuel Injection System	Electronic
Engine Model	Doosan DL06

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Cooling System	Ok
Coolant	Ok
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok, Minor Dents
Protective Covers & Sheets	Ok, Under Swing Cover Is Missing
Engine Hood	Ok
Side Access Doors	Ok, Left Door Minor Dent
Steps And Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Not Functional
Battery Check	Need Change
Cabin Compartments	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok, Left Cylinder Minor Leak
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok, Minor Leak

Performance Analysis

Boom Pins Condition	Ok
Excavator Self- Drift Test	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Arm Pins Condition	Ok, Minor Loose
Hydraulic Pump Noise Check	Ok, Little Noisy
Bucket Pins Condition	Ok, Minor Loose, Washer Is Missing
Slewing Ring Bearing Movement Check	Ok
Swing Drive And Brake Test	Ok
Drive Force Test	Ok

Attachments

Attachments Model	Bucket
Size	W1250, H1000, D800 (Mm)
Status	Ok, Minor Dents And Welding
Coupler Status	Ok
Second Attachments Model	N/A
Size	N/A
Status	N/A

Undercarriage

Bushings	40%
Track Shoes	Right 70% - Left 50%
Idlers	80%
Shoe Width In Mm:	600 Mm
Track Pitch In Mm:	55 Mm
Carrier Rollers	40%
Track Rollers	30%
Track Links	Right 60% - Left 50%
Sprocket Segments	Right 70% - Left 50%

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

