

Inspection report – 2016 JCB 3DX

Serial No: HAR3DXSUL01495014 | Hours: 2802 | Location: Dubai, United Arab Emirates | SKU: 806

Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	N/A
Auxiliary Lines	N/A
4WED	Yes
Extended Stick	N/A
Rear Quick Coupler	N/A
All Wheel Steer	N/A
Fork	N/A
Emission Compliance Label	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	N/A
Dashboard Screen, Gauges	Ok, Speed gauge not functional
Warning alarms message	Ok
Washer, Wipers	Not functional
Air Condition & Heating System	N/A
Cab Floor Covering	Ok, Minor cut
Cab Structure	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	JCB 444
Engine Cooling System	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Oil need change
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, Normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok, Repainted
Sheet Metal	Ok
Wheel Fenders	Ok
Lights Check	Ok
Battery Check	Ok
Boom	Ok
Stick	Ok
Stick Extension	N/A
Rims, Wheel Nuts	Ok, 1 nuts missing
Loader Frame & Hinges	Ok

Power Train Inspection

Axles and Differentials	Ok
Transmission Leak	Ok
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Manual

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok
Swing Cylinders	Ok
Boom Cylinder	Ok
Stick Cylinder	Ok
Bucket Cylinder	Ok
Clamshell Cylinder	Ok

Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Loader Stall Test	Ok
Braking System Test	Ok, Park break need maintenace
Pins Boom	Ok, Minor loose
Pins Stick / Extension	Ok, Minor loose
Rear Bucket Linkage	Ok
Loader Pins & Hinges	Ok, Minor loose
Outriggers & Pads	Ok
Boom Side Tilt	Ok

Attachments Estimated Remaining Life %

Front Bucket	-
Size	W2150, H1000, D500 mm
Condition	Ok
Rear Bucket	-
Size	W760, H720, D500 mm
Condition	Ok
Attachment Coupler	Ok

Tires Estimated Remaining Life %

Front Right	-
Tire Brand & Size Details	CEAT 15.5/80-18
Tire Remaining Life Percentage	80%
Tire Condition Notes	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Front Left	-
Tire Brand & Size Details	MRF 15.5/80-18
Tire Remaining Life Percentage	60%
Tire Condition Notes	Ok
Rear Right	-
Tire Brand & Size Details	JCB 16.9-28
Tire Remaining Life Percentage	70%
Tire Condition Notes	Not Original
Rear Left	-
Tire Brand & Size Details	JCB 16.9-28
Tire Remaining Life Percentage	70%
Tire Condition Notes	Not Original

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

