

Inspection report – 2017 Hyundai Robex 500LC-7

Serial No: HHKHN02AE0000901 | Hours: 9602 | Location: Dubai, United Arab Emirates | SKU: 1092

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	-

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, mirrors missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Wiper missing
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection System	Electrical
Engine Model	cummins QSM11

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Cooling System	Ok
Coolant	Ok
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok, Counterweight minor crack
Arm Condition	Ok
Lights	Ok, need 3 bulbs
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

Performance analysis

Boom Pins Condition	Ok
Excavator self- Drift Test	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok

Attachments

Attachments model	Bucket
Size	W580, H1450, D1150 mm
Status	Ok
Coupler status	Minor crack
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

bushings	70%
Track shoes	70%
idlers	L60%, R70%
shoe width in mm:	600
track pitch in mm:	80
carrier rollers	70%
Track rollers	60%
Track links	60%
Sprocket segments	80% left side minor leak

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

