

Inspection report – 2018 Massey Ferguson MF7720

Serial No: VKKMX65EVJB108015 | Hours: 3208 | Location: Dubai, United Arab Emirates | SKU: 1012

Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency A/C	N/A
PTO	Yes
4WED	Yes
All Wheel Steer	N/A
3-Point Linkage	Yes
Drawbar	Yes
Emission Compliance Label	N/A
Horn Function	N/A
Closed Cabin	Yes
CE Specification	Yes
Shift Speed Controller	Yes
Front Axle Suspension	Yes
Cabin Suspension	Yes
Engine Speed Memory Control	Yes
DEF	Yes
Spool valve	Yes
Crous control	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok, main control lever is broken
Windows and Mirrors	Ok, left side glass broken, front left mirror missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Service light is on

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Washer, Wipers	Ok, rear not functional
Air Condition & Heating System	Not Functional
Cab Floor Covering	Ok
Cab Structure	Ok
Electrical System	Need Service

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	AGCO POWER 200 Hp (147 Kw)
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Need change
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Steering Linkage	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Sheet Metal	Ok, engine side sheets missing
Wheel Fenders	Ok
Lights Check	Not Functional
Battery Check	Need change
Rims, Wheel Nuts	Ok

Power Train Inspection

Axles and Differentials	Ok
Transmission Leak	Ok
Power Train force	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi- Auto 4 gear

Hydraulic System

Hydraulic Leaks	Ok, minor
Remote Hydraulic Controls	Not tested
Steering Hydraulic Jacks	Not tested
Hydraulic Pumps and Valves	Not tested
Cylinder(s)	Not tested

Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Cylinder Pins and Bushings	Not tested
Braking System Test	Ok
Spool Valve Electronic/ Manual	Not tested

Tires Estimated Remaining Life %

Front Right	-
Tire Brand & Size Details	RUNGOD 18.4- 30
Tire Remaining Life Percentage	40%
Tire Condition Notes	Ok
Front Left	-
Tire Brand & Size Details	BKT 18.4- 30
Tire Remaining Life Percentage	90%
Tire Condition Notes	Ok
Rear Right	-
Tire Brand & Size Details	Galaxy 650/65R42
Tire Remaining Life Percentage	80%
Tire Condition Notes	Ok
Rear Left	-
Tire Brand & Size Details	Galaxy 650/65R42
Tire Remaining Life Percentage	90%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Condition Notes

Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

