

PLANT & EQUIPMENT

Inspection report – 2018 TATA Daewoo K6DVF

Serial No: KLTK6DVF1JK000008 | Location: Dubai, United Arab Emirates | SKU: 1109

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	N/A
Hill stand aid function	Yes
Horn off-on	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Navigation	N/A
ABS	Yes
Driver bed	Yes
Moving off aid	N/A
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	N/A
Radio	N/A
TRC	N/A
Camera sensor	N/A
Differential lock	Yes
Advanced emergency brake assist	Yes

Truck Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Need minor service, 2 door lock need replase
Controls, Levers	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Windows and Mirrors	1 mirror glass missing, 1 mirror missing, front glass broken
Dashboard Screen, Gauges	Not functional
Warning alarms message	Not functional
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Need service
Interior, Covers	Need service
Passenger Seat	Need upholstery
Radio	N/A
Starting	Start directly from the starter and off directly from the fuel pump

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	Doosan DV15TIS
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Chassis, Frames	Ok, minor rust
Frame Stamp Serial Number	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok, need service
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Front bumper need repair
Lights / Batteries	Not functional, need 6 bulbs

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Fenders	Ok
Suspension Springs/Hangers	front and rear spring leaves need service
Suspension Bushings	Ok

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok, minor leak
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Manual
Clutch	Ok

Truck Limited Functional Test

Transmission Forward	Not functional
Transmission Reverse	Not functional
Steering	Functional
Automatic Group Select	N/A
Service Brake	Functional
Park Brake	Functional
Electrics	Need service
Retarder	Functional

Hydraulics

PTO Pump	Functional
hydraulic cylinder	Functional, minor leak from lifting cylinder
cabine lift cylinder & valve	Ok, right cylinder minor leak

Tires

Axle 1 / RHS mm (%) / LHS mm (%)	R60%, L40%
Axle 2 Inside / RHS mm (%) / LHS mm (%)	R40%, L40%
Axle 2 Outside / RHS mm (%) / LHS mm (%)	R20%, L20%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Axle 3 Inside / RHS mm (%) / LHS mm (%)	R70%, L40%
Axle 3 Outside / RHS mm (%) / LHS mm (%)	R50%, L60%
Tire Size	-

Cargo box

Size	L 5400 , W 27500 , H 1400 mm
Condition	Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

