

Rapport d'inspection – 2012 Hyster H9.0FT

Numéro de série: A299E01624K | Lieu: Dubai, Émirats arabes unis | SKU: 1091

Key Features & Condition

Safety Certification Label	Yes
Fork Extension	N/A
Draw Bar	Yes
Back-up Alarm	Yes
Head Lights	Yes
Seat Belt	N/A
Air Condition	N/A
Propane Tank	N/A
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	N/A
Control Levers, Control Stick	Ok
Windows and Mirrors	N/A
Dashboard Screen, Gauges	N/A
Warning alarms message	N/A
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Gard	Ok
Electrical System	Need service

Engine & Performance

Fuel Injection System	Electronic
Engine Model	Cummins QSB3.3
Engine Cooling System	Ok
Engine Oil Check	Ok
Coolant	Normal water

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Minor
Leaks & Seals	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Sheet Metal	Ok
Door Handles	N/A
Cooler Grill	Ok
Counterweight	Ok
Lights	Ok
Batteries	Ok
Exterior Paint Condition	Ok

Transmission

Axels	Ok
Gearbox	Ok
Universal Joints	Ok
Differentials	Ok
Brake Drums/Disk	Ok
Clutch	N/A

Hydraulic System

Hoses & Lines	Ok
Pump And Valve Bloc	Functional
Lift & Tilt Cylinders	Ok
Fork side shift Cylinder	Ok
Steering Cylinder	Ok
Fork Open-Close Cylinder	N/A

Limited Functional Test

Drive Forward	Ok
---------------	----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Drive Reverse	Ok
Service Brake	Ok
Steering	Ok
Wheel Bearing	Ok
Park Brake	Ok
Lift, Tilt, Control	Ok
Fork side shift	Ok

Tools

Mast, size & condition	2200 mm
Fork 1, Size & Type, Condition	L2500, W150 mm
Fork 2, Size & Type, Condition	N/A

Tires Condition %

<html>Axle 1 RHS mm (%) </html>	70%
<html>Axle 1 LHS mm (%)</html>	70%
<html>Axle 2 RHS mm (%) </html>	70%
<html>Axle 2 LHS mm </html>	70%

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

