

Rapport d'inspection – 2013 Volvo L105

Numéro de série: VCE0L105C00001073 | Heure: 15275 | Lieu: Dubai, Émirats arabes unis | SKU: 1023

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok, left mirror broken
Dashboard Screen, Gauges	Ok
Warning alarms message	Park break failure/ reduced shift function
Washer, Wipers	Ok
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok, not original
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Model	Volvo D7D
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok, repainted
Counterweight Condition	Ok
Wheel Fenders	Ok
Lights Check	2- Ok, 4 not functional
Battery Check	Ok

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok
Power Train force	weak du to park break
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi- auto

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Loader Stall Test	Ok
Brake System Test	Ok
Articulation Movement Check	Ok
Loader Attachment Pins	Ok

Attachments

Bucket Width and Capacity	W1350, h1250, d950 mm
Bucket Bottom Condition	Ok
Bucket Edge & Teeth Condition	Ok
Bucket Side Condition	Ok
Attachment Coupler	Ok

Tires Inspection

Front Right	-
Tire Brand & Size Details	China 23.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New, tube type
Wheel Rims & Nuts	Ok
Front Left	-
Tire Brand & Size Details	China 23.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New, tube type
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	Green 23.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New, tube type
Wheel Rims & Nuts	Ok
Rear Left	-
Tire Brand & Size Details	Gann shan 23.5-25
Tire Remaining Life Percentage	100%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Condition Notes

New, tube type

Wheel Rims & Nuts

Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

