

PLANT & EQUIPMENT

Rapport d'inspection – 2014 TATA Daewoo M9AVF

Numéro de série: KL3M9AVF1EK000608 | Lieu: Dubai, Émirats arabes unis | SKU: 1112

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	N/A
Hill stand aid function	N/A
Horn off-on	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	Not cooling
Navigation	N/A
ABS	Yes
Driver bed	Yes
Moving off aid	N/A
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	N/A
Radio	N/A
TRC	N/A
Camera sensor	N/A
Differential lock	Yes
Advanced emergency brake assist	Yes
Water Tank	Yes

Truck Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Need service door lock need repair



PLANT & EQUIPMENT

Controls, Levers	Need service
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Not functional
Warning alarms message	Not functional
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Need minor service
Interior, Covers	Ok
Passenger Seat	Need upholstery
Radio	N/A
Electrical System	Need minor service

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	DV15TIS
Engine Cooling System	Radiator broken
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok, minor welding
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	N/A, radiator broken
Fluid Leaks	Minor leak from engine head, oil sump
Starting	Direct from starter

Exterior Condition & Visual Inspection

Chassis, Frames	Ok, minor rust
Frame Stamp Serial Number	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok, need minor service
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Front bumper need replace
Lights / Batteries	Front signal lights missing, need 4 bulbs

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Fenders	Ok
Suspension Springs/Hangers	Ok, front and rear spring leafs minor loose
Suspension Bushings	Ok
Water Tank	Ok

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok, minor loose
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok, minor leak
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Normal
Clutch	Ok

Truck Limited Functional Test

Transmission Forward	Ok
Transmission Reverse	Ok
Steering	Ok
Automatic Group Select	N/A
Service Brake	Ok
Park Brake	Ok
Electrics	Need service
Retarder	Ok

hydraulics

PTO Pump	N/A
Water pump	Not tested
cabine lift cylinder & valve	Not functional, leaks

Tires

Axle 1 / RHS (%) / LHS (%)	L70%, R70%
Axle 2 / RHS (%) / LHS (%)	L60%, R 70%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Axle 3 Inside / RHS (%) / LHS (%)	L60%, R30%
Axle 3 Outside / RHS (%) / LHS (%)	L50%, R40%
Axle 4 Inside / RHS (%) / LHS (%)	L70%, R40%
Axle 4 Outside / RHS (%) / LHS (%)	L70%, R30%
Tire Size	315/80 R22.5

Water Tank

size	5000 gallon
condition	Ok, minor dent

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

