

Rapport d'inspection – 2015 Caterpillar D6R XL

Numéro de série: CAT00D6RAJEN00313 | Heure: 15874 | Lieu: Dubai, Émirats arabes unis | SKU: 991

Key Features & Condition

| | |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Ground Ripper | N/A |
| Ripper Control Valve | N/A |
| Low Ground Pressure Tracks | N/A |
| Operator's Manual | N/A |
| Emission Compliance Label | N/A |
| Grade Control System | N/A |
| Equipment Parts Manual | N/A |
| CAT System One | N/A |
| Horn | N/A |

Operator Cabin Details

| | |
|-----------------------------------|-------------------------------------|
| Seat and Arm Support | Ok |
| Cab Doors & covers | Ok |
| Controls, Levers | Ok |
| Windows and Mirrors | Ok |
| Dashboard Screen, Gauges | Ok |
| Warning alarms message | Ok |
| Washer, Wipers | Ok |
| Air Conditioning & Heating System | Not Functional |
| Cab Floor Covering | N/A |
| Cab Structure, Gard | N/A |
| Electrical System | Ok, need minor service (Engine RPM) |

Engine & Performance

| | |
|-----------------------|------------|
| Fuel Injection Type | Electronic |
| Engine Model | C9 |
| Engine Cooling System | Ok |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|-------------------------|
| Engine Oil Check | Ok |
| Blowby | Normal |
| Exhaust System & Muffler | Ok |
| Belts & Air/Oil Filters | Ok, filters need change |
| Smoke | Minor |
| Coolant | Ok, normal water |
| Fluid Leaks | Ok, minor gasket leak |
| Fuel System | Need minor service |

Exterior Condition & Visual Inspection

| | |
|-----------------------------------|---|
| Push Frame & Trunnions | Ok |
| Doors, Covers, and Grilles | Ok |
| Access Steps & Handrails | Ok |
| Exterior Paint Condition | Ok |
| Blade Trunnions & Bushings | Ok |
| Underbody Protection Plates | Ok |
| Final Drive Condition | Functional |
| Fuel Tank, Roof, & Hood Condition | Ok |
| Lights and Battery Check | Need battery and terminals, rear lights missing |
| Push Arm Pivot Shaft | Ok |
| Tilt Linkage Pins & Bushings | Ok |

Hydraulic System

| | |
|------------------------------|-----|
| Hydraulic Leaks | Ok |
| Lift Hydraulic Jacks | Ok |
| Ripper Lift Hydraulic Jacks | N/A |
| Tilt Hydraulic Jack | Ok |
| Angle Hydraulic Jack | N/A |
| Ripper Angle Hydraulic Jacks | N/A |

Limited Functional Testing & Operation

| | |
|-----------------|-----|
| Push Frame Pins | Ok |
| Blade Pins | Ok |
| Ripper Pins | N/A |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|------------|
| Equalizer Bar Condition | Ok |
| Bulldozer Stall Test | Ok |
| Steering Function Test | Ok |
| Blade Tilt and Lift Test | Ok |
| Undercarriage Pivot Pins | Ok |
| Transmission Test | Functional |
| Brake System Test | Ok |
| Torque Converter Test | Functional |

Blade Inspection

| | |
|-----------------------|----|
| Blade Base Condition | Ok |
| Spill Rack Condition | Ok |
| Blade Front Condition | Ok |
| Blade Edge Condition | Ok |

Undercarriage Inspection

| | |
|-------------------------------|-----|
| Right Side Undercarriage Wear | - |
| Undercarriage Bushings | 80% |
| Undercarriage Shoes | 70% |
| Front Idler Condition | 90% |
| Rear Idler Condition | 90% |
| Carrier Roller Condition | 90% |
| Track Links Condition | 90% |
| Sprocket Condition | 90% |
| Roller Condition | 90% |
| Track Canon Condition | 70% |
| Left Side Undercarriage Wear | - |
| Undercarriage Bushings | 80% |
| Undercarriage Shoes | 70% |
| Front Idler Condition | 90% |
| Rear Idler Condition | 90% |
| Carrier Roller Condition | 90% |
| Track Links Condition | 90% |
| Sprocket Condition | 90% |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT | AUCTIONS

| | |
|-------------------------|---------------|
| Roller Condition | 90% |
| Track Canon Condition | 70% |
| Track Width Measurement | W560, L230 mm |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

