

Rapport d'inspection – 2015 Manitou MT-X 1840

Numéro de série: 948609 | Heure: 20831 | Lieu: Dubai, Émirats arabes unis | SKU: 1090

Key Features & Condition

Safety Certification Label	N/A
Axle Based 4WD	Yes
Electric Powered	N/A
Equipment Parts Manual	N/A
Electric Operating System	N/A
Horn Function	N/A
Travel Alarm	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Diesel Powered	Yes
Distinct Steering Modes	Yes

Operator Cabin Details

Seat and Arm Support	Ok, need upholstery
Cabin Door	Need lock repair
Control levers, Control swithes	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Dtc 220028, 2d0038, 820389, 030026, 03000c, 030027, 030027,030023, 030029, a203ff, a203fe, a204b0, a204d1, a203e9.
Electrical System	Need minor service
Windows/ mirrors/ Wipers	Ok, front window need polish, rear and side wipers not functionl
Floor Mats	Ok
Air Conditioning & Heating System	Not functional

Engine

Model	Perkins nm75-284
Injection Type	Electronic
Leaks	Minor leak

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Oil Condition	Ok
Exhaust Smoke	Minor
Cooling System	Ok
Coolant	Ok, normal water
Sound	Ok
Blow By	Normal
Belts	Ok
Power	Ok

Exterior Condition & Visual Inspection

Chassis	Ok, Telescopic boom cylinder base welded
Sheet Metal	Ok
Engine hood	Ok, minor crack
Boom Condition	Ok
Boom Linkage / Guides	Ok
Paintwork	Ok
Cooler Grill	Ok
Frame Condition	Ok
Outriggers	Ok
Batteries	Ok
Lights	Ok
Fenders	Ok

Hydraulic System

Hoses, Lines, Swivel	Ok
Pump And Valve Bloc	Functional
Steering Cylinder	Ok, 3 minor leak
Boom Lift Cylinder(s)	Ok
Bucket cylinder	Ok, minor leak
Telescopic Boom Cylinders	Ok, minor leak
Carriage Tilt Cylinder	Ok
Frame Leveling Cylinders	Ok
Stabilizer Cylinders	Ok
Leaks	Ok, minor leaks

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Drivetrain

Transmission	Functional
Transfar Gear type	Manual
Transfer Case / Drop Box	Ok
Front / Rear Axle	Ok

Limited Functional Testing & Operation

Drive Forward	Ok
Drive Reverse	Ok
Steering	Ok
Platform Function Controls	Ok
Boom Extension	Ok
bucket angle movment	Ok
Wheel Bearing	Ok
brake system	Ok
Lifting	Ok

Tires condition / Type / Size

Axle 1 Right	50%
Axle 1 Left	40%
Axle 2 Right	40%
Axle 2 Left	40%

Attachments

Coupler Condition	Ok, minor welding
Tool1	Bucket
Size	W 2200, D 550, H 850.
Condition	Ok
Tool 2	N/A
Size	N/A
Condition	N/A

Disclaimer

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

