

PLANT & EQUIPMENT

Rapport d'inspection – 2015 New Holland B90B

Numéro de série: FNH0B90BNFHH01165 | Heure: 11822 | Lieu: Dubai, Émirats arabes unis | SKU: 1170

Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	Not cooling
Auxiliary Lines	N/A
4WED	Yes
Extended Stick	N/A
Rear Quick Coupler	Yes
All Wheel Steer	Yes
Fork	N/A
Emission Compliance Label	N/A
Horn Function	Not functional
Jack Hammer Line	N/A
Radio	N/A
Tools	N/A
Operation Manual	N/A
Greas Pump	N/A

Operator Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Ok, glass need polish
Controls, Levers	Levers need minor service
Windows and Mirrors	Front and side glass broken
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Rear wiper missing
Air Condition & Heating System	Not cooling
Cab Floor Covering	Ok
Cab Structure	Ok



PLANT & EQUIPMENT

Electrical System

Need minor service, starts direct from starter

Engine & Performance

Fuel Injection Type

Mechanical

Engine Model

4.5 litre FPT Industrial engine

Engine Cooling System

Ok

Engine Oil Check

Ok, need change

Blowby

Minor

Exhaust System & Muffler

Ok

Belts & Air/Oil Filters

Ok

Smoke

Minor white smoke

Coolant

Coolant

Fluid Leaks

Minor leak from head gasket, rear cover

Fuel Pump

Fuel system need service

Exterior Condition & Visual Inspection

Chassis

Ok

Engine Hood

Ok

Access Steps and Handrails

Ok

Exterior Paint Condition

Ok

Sheet Metal

Ok

Wheel Fenders

Ok

Lights Check

Need 4 bulbs

Battery Check

Ok

Boom

Ok

Stick

Ok

Stick Extension

Ok

Rims, Wheel Nuts

Ok

Loader Frame & Hinges

Ok

Power Train Inspection

Axles and Differentials

Ok, diffraction minor leak

Transmission Leak

Ok

Power Train force

Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Manual, electrical control

Hydraulic System

Hydraulic Leaks	Minor leak from control valve
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Functional
Swing Cylinders	Ok
Boom Cylinder	Ok
Stick Cylinder	Ok
Bucket Cylinder	Ok
Clamshell Cylinder	N/A

Limited Functional Testing & Operation

Steering Function Test	Functional
Transmission Operation Test	Functional
Loader Stall Test	Functional
Braking System Test	Functional
Pins Boom	Ok
Pins Stick / Extension	Minor welding right jack pin
Rear Bucket Linkage	Ok
Loader Pins & Hinges	Ok
Outriggers & Pads	Ok
Boom Side Tilt	N/A

Attachments Estimated Remaining Life %

Front Bucket	-
Size	H900, W2300, D550 mm
Condition	Ok
Rear Bucket	-
Size	H700, W700, D450 mm
Condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Attachment Coupler

Ok

Tires Estimated Remaining Life %

Front Right

-

Tire Brand & Size Details

Ozka 12.5/80-18 Tube Type

Tire Remaining Life Percentage

50%

Tire Condition Notes

Ok

Front Left

-

Tire Brand & Size Details

Ozka 12.5/80-18 Tube Type

Tire Remaining Life Percentage

70%

Tire Condition Notes

Ok

Rear Right

-

Tire Brand & Size Details

Farm boy 16.9-28 Tube Type

Tire Remaining Life Percentage

70%

Tire Condition Notes

Ok

Rear Left

-

Tire Brand & Size Details

Ozka 16.5-28 Tube Type

Tire Remaining Life Percentage

70%

Tire Condition Notes

Ok

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

