

Rapport d'inspection – 2015 Tadano GR-600EX

Numéro de série: 549126 | Heure: 27731 | Lieu: Dubai, Émirats arabes unis | SKU: 1014

Key Features & Condition

| | |
|--------------------|-----|
| CE Labeling | N/A |
| Automatic Shift | Yes |
| Semi-Automatic | N/A |
| Tachograph | N/A |
| Auto Lube | N/A |
| A/C | N/A |
| Extended Fuel tank | N/A |
| Retarder | Yes |
| 2 Axle Steering | Yes |

Truck Cab

| | |
|---------------------|--------------------------------|
| Driver Seat | Ok, need seat cover |
| Switches, Levers | Ok |
| Gauges, Warn Lights | Screen need service (sunburnt) |
| Aircon / Heater | N/A |
| Cab Doors | Ok |
| Windows, Mirrors | Ok |
| Wipers, Washers | Ok |
| Interior, Covers | Ok |

Engine

| | |
|-----------------|--------------------|
| Injection Type | Mechanical |
| Engine Model | mitsubishi 8m80-tl |
| Leaks, Seals | Ok |
| Oil Condition | Ok |
| Exhaust/Muffler | Ok |
| Cooling System | Ok |
| Smoke, Fume | Normal |
| Blow By | Normal |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|-------------------|----|
| Belts, Pulleys | Ok |
| Coolant Condition | Ok |

Visual inspection exterior

| | |
|---------------------|----------------|
| Chassis, Frames | Ok |
| Sheet Metal, Covers | Ok, minor rust |
| Steps, Grab Irons | Ok |
| Paintwork | Ok |
| Cooler Grill | Ok |
| Bumpers | Ok |
| Lights | Not functional |
| Batteries | Need replace |
| Main Hook | Ok |
| Auxiliary Hook | N/A |

Power Train

| | |
|---------------------|-----------|
| Axels/Differentials | Ok |
| Stabilizers, Beams | Ok |
| Rubber Sleeves | Ok |
| Brake Pads/Disks | Ok |
| Compressor | Ok |
| Transfer Gear | Ok |
| Universal Joints | Ok |
| Transmission | Automatic |
| Clutch | N/A |

Hydraulics / Steering

| | |
|--------------------|----|
| Hoses & Lines | Ok |
| Hydraulic Pump | Ok |
| PTO | Ok |
| Steering Cylinders | Ok |
| Steering Linkage | Ok |
| Lift Limitations | Ok |
| Outriggers | Ok |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Crane Condition / Limited Test

| | |
|-----------------------|-----|
| Drive Forward & Back | Ok |
| Controls, Levers | Ok |
| Boom Conditions | Ok |
| Telescopic Segments | Ok |
| Hydraulic Cylinders | Ok |
| Swing Bearing / Drive | Ok |
| Hose Lines | Ok |
| Lift Limitations | Ok |
| Main Hook | Ok |
| Auxiliary Hook | N/A |
| Outriggers | Ok |

Tires Condition %

| | |
|--------------|---------------------|
| Right | - |
| Axle 1 | 60% |
| Axle 2 | 60% |
| Left | - |
| Axle 1 | 60% |
| Axle 2 | 80% |
| Size / Brand | 29.5-25 Bridgestone |

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

