

## Rapport d'inspection – 2016 Manitou 200ATJ

Numéro de série: 959602 | Lieu: Dubai, Émirats arabes unis | SKU: 1098

---

### Key Features & Condition

|                            |     |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Diesel Powered             | Yes |
| Electric Operating System  | Ok  |
| Travel Alarm               | Ok  |
| Axle Based 4WD             | Ok  |
| Upper Control Station      | Ok  |
| Horn                       | Ok  |
| extension Boom             | Ok  |
| Machine control panel      | Ok  |

---

### Engine

|                |                     |
|----------------|---------------------|
| Model          | kubota V2403-m-eu35 |
| Injection      | Mechanical          |
| Oil Condition  | Need change         |
| Exhaust        | Ok                  |
| Cooling System | Ok                  |
| Coolant        | Normal water        |
| Leaks          | Ok                  |
| Sound          | Ok                  |
| Blow By        | Normal              |
| Belts          | Ok                  |
| Power          | Ok                  |

---

### Exterior

|              |                                                      |
|--------------|------------------------------------------------------|
| Chassis      | Ok                                                   |
| Sheet Metal  | Ok, battery cover and engine side cover are missing, |
| Engine Hoods | Broken                                               |
| Control Hood | Cracked                                              |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                    |                       |
|--------------------|-----------------------|
| Steps/Ladders      | Ok                    |
| Boom Linkage       | Ok                    |
| Paintwork          | Ok                    |
| Cooler Grill       | Ok                    |
| Frame Condition    | Ok                    |
| Diesel Tank        | Tank cover is missing |
| Lights             | Ok                    |
| Platform Condition | Ok                    |
| Batteries          | Ok                    |

---

## Hydraulics

|                             |                 |
|-----------------------------|-----------------|
| Hoses,Lines,Swivel          | Ok, minor leake |
| Pump And Valve Bloc         | Ok              |
| Steering Cylinder           | Ok              |
| Platform angle cylinder     | Ok              |
| Articulating Boom Cylinders | Ok              |
| Jip Cylinder                | Ok              |
| Platform Rotation Cylinder  | Ok              |
| Telescopic jack             | Minor leak      |

---

## Limited Functional Test

|                                 |              |
|---------------------------------|--------------|
| Drive Forward                   | Ok           |
| Drive Reverse                   | Ok           |
| Steering                        | Ok           |
| carriage Function Controls      | Need service |
| Boom Extension                  | Ok           |
| 360° Continuous turret rotation | Ok           |
| Platform angle                  | Ok           |
| Wheel Bearing                   | Ok           |
| Platform control                | Ok           |
| brake system                    | OK           |
| Lifting                         | Ok           |
| Platform Rotation               | Ok           |
| Jib                             | Ok           |



---

## Tires

|              |     |
|--------------|-----|
| Axle 1 right | 20% |
| Axle 1 left  | 20% |
| Axle 2 right | 20% |
| Axle 2 left  | 20% |

---

## Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

