

Rapport d'inspection – 2017 Komatsu PC400LC-8R

Numéro de série: KMTPC196LHXJ31084 | Heure: 14692 | Lieu: United Arab Emirates | SKU: 847

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A
Radio	Ok

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	N/A
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection System	Elecetronic
Engine Model	Komatsu SAA6D125E-5

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Coolant	Ok, normal water
Exhaust System & Muffler	Ok, muffler minor welded
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

Exterior Condition & Visual Inspection

Chassis Punching Number	Ok, Visual
Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok, lock need repair
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok, minor welding on arm pin side
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok, minor welding on coupler pin side
Lights	Ok
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok, some parts repainted

Hydraulic System

Hydraulic Leaks	Ok, fittings minor leaks
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

Performance analysis

Boom Pins Condition	Ok
Excavator self- Drift Test	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok

Attachments

Attachments model	Bucket
Size	W1250\H1300\D850 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

Bushings	20%
Track Shoes	30%
Idlers	40%
Shoe Width In Mm:	800mm
Track Pitch In Mm:	80mm
Carrier Rollers	40%
Track Rollers	30%
Track Links	30%
Sprocket Segments	60%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

