

## Rapport d'inspection – 2018 Caterpillar 323D3

Numéro de série: CAT0323DPFEY00230 | Heure: 3835 | Lieu: Dubai, Émirats arabes unis | SKU: 895

---

### Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A
Rear Camera	N/A
E-Cataloge	N/A
Radio	N/A

---

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, left mirror is missing
Dashboard Screen, Gauges	Ok, cover has scratches
Warning Alarms Message	Ok, service required
Washer, Wipers	N/A
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok, minor cut
Cab Structure, Guard	Ok
Electrical System	Ok, need minor service

---

### Engine & Performance

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Fuel Injection System	Mechanical
Engine Model	C7.1 1106C – 6 cylinder mechanical injection
Engine Cooling System	Ok
Engine Oil Check	Ok
Coolant	Ok, normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, filters need change
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

---

## Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok, minor welding
Protective Covers & Sheets	Ok
Engine Hood	Ok, needs lift holder
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok, minor welding on bucket pin side
Lights	Ok
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok, repainted

---

## Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

---

## Performance analysis

Boom Pins Condition	Ok
---------------------	----

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Excavator self- Drift Test	Ok
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok, minor loose
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok

---

## Attachments

Attachments model	Bucket
Size	W1260, H1100, D750 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

---

## Undercarriage

Bushings	L 60%, R40%
Track Shoes	80%
Idlers	70%
Shoe Width in mm:	600 mm
Track Pitch in mm:	75
Carrier Rollers	70%
Track Rollers	60%
Track Links	60%
Sprocket Segments	L 60%, R40%

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

