

Rapport d'inspection – 2018 Caterpillar 349D2L

Numéro de série: CAT0349DTTAH10020 | Heure: 6510 | Lieu: Dubai, Émirats arabes unis | SKU: 896

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	Yes
Rear Camera	N/A
E-Cataloge	N/A
Radio	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, no mirrors
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok, water sperator full
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok, minor cut
Cab Structure, Guard	Ok
Electrical System	Ok

Engine & Performance

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Fuel Injection System	Electronic
Engine Model	Cat® C13 ACERT™
Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Coolant	Ok
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, filters need change
Smoke Check	Minor
Blowby	Normal
Leaks & Seals	Ok, minor oil leak from rockers gasket, starter gasket

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Ok, no boom light
Battery Check	Need replace
Cabin Compartments	Ok, no fues cover
Exterior Paint Condition	Ok, repainted

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok, reversed control

Performance analysis

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Boom Pins Condition	Ok
Excavator self- Drift Test	Ok
Arm Pins Condition	Minor loose
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Minor loose, need bush and lock
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok

Attachments

Attachments model	Bucket
Size	W1600, H1550, D1300 mm
Status	Ok, Pins need new buch
Coupler status	Ok, Pins need new buch
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

Bushings	40%
Track Shoes	50%
Idlers	50%
Shoe Width in mm:	750 mm
Track Pitch in mm:	80 mm
Carrier Rollers	60%
Track Rollers	50%
Track Links	50%
Sprocket Segments	50%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

