

Rapport d'inspection – 2022 Caterpillar 216B3 (UNUSED)

Numéro de série: CAT0216BAPWK05582 | Heure: 7 | Lieu: United Arab Emirates | SKU: 774

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Yes
Emission Compliance Label	N/A
Attachment Coupler	N/A
Horn Function	Yes
Closed Cabin	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok
Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	C2.2
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Leaks& seals	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Protective Covers & Sheets	Ok
Engine Door	Ok
Lights	Ok
Battery Check	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Hydraulic Pumps and Valves	Ok

Limited Functional Testing & Operation

Steering Function Test	Ok
Skid steer Stall Test	Ok
Brake System Test	Ok
Attachment Pins	Ok
Final Drive Motors Test	Ok
Electrical System Check	Ok

Attachments

First Attachments model	Bucket
Size	W 1530, H700 , 0.36 m ³
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Status

N/A

Tires Estimated Remaining Life %

Front Right	100%
Front Left	100%
Rear Right	100%
Rear Left	100%
Size	10.16.5
Type	Tubeless
Wheel Rims & Nuts	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

