

## Rapport d'inspection – 2023 XCMG XCT80

Numéro de série: LXGCPA508PA003739 | Km: 7408 | Lieu: Dubai, Émirats arabes unis | SKU: 854

---

### Key Features & Condition

CE Labeling	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Extended Fuel tank	N/A
Retarder	N/A
Rear Axle Lifter	N/A
2 Axle Steering	Yes

---

### Truck Cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Gauges functional, screen is not functional
Aircon / Heater	Not cooling
Passenger Seat	Ok
Cab Doors	Ok
Windows, Mirrors	Ok, right small mirror cracked
Wipers, Washers	Ok
Interior, Covers	Ok
Radio	Ok

---

### Crane operator cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Ok
Aircon / Heater	N/A
Cab Doors	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Windows	Ok
Wipers	Ok
Interior Covers	Ok

---

## Engine

Injection Type	Electronic
Engine Model	wp12.375e50
Leaks, Seals	Ok
Oil Condition	Ok
Exhaust/Muffler	Ok
Cooling System	Ok
Smoke, Fume	Normal
Blow By	Normal
Belts, Pulleys	Ok
Coolant Condition	Ok, normal water

---

## Visual inspection exterior

Chassis, Frames	Ok, minor welding
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok, repainted
Cooler Grill	Ok
Bumpers	Ok
Lights	Ok

---

## Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Wear-Out
Brake Pads/Disks	Ok
Compressor	Functional
Transfer Gear	Manual, need minor service
Universal Joints	Ok
Transmission	Functional

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Clutch

Need service

---

## Hydraulics / Steering

Hoses & Lines	Ok
Hydraulic Pump	Ok
PTO	Ok
Steering Cylinders	Ok
Steering Linkage	Ok

---

## Carrier Limited Functional Test

Transmission Forward	Functional hard gear shift
Transmission Reverse	Functional hard gear shift
Automatic Group Select	N/A
Service Brake	Functional
Park Brake	Functional
Electrics	Functional
Retarder	Not tested

---

## Crane Condition / Limited Test

Controls, Levers	Functional
Boom Conditions	Ok
Telescopic Segments	Ok
Hydraulic Cylinders	Ok
Swing Bearing / Drive	Functional
Hose Lines	Ok
Lift Limitations	Not functional
Hook	Ok
Outriggers	Functional

---

## Tires Condition %

Right	-
Axle 1	60%
Axle 2 Inside	50%
Axle 3 Outside	70% (2019 Need change)

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



# PLANT & EQUIPMENT | AUCTIONS

Axle 3 Inside	70% (2019 Need change)
Axle 4 Outside	60% (2019 Need change)
Axle 4 Inside	60% (2019 Need change)
Left	-
Axle 1	60%
Axle 2 Inside	50%
Axle 3 Outside	60% (2019 Need change)
Axle 3 Inside	60% (2019 Need change)
Axle 4 Outside	60% (2019 Need change)
Axle 4 Inside	40% (2019 Need change)

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

