PLANT & EQUIPMENT | AUCTIONS

# Rapport d'inspection – 2024 Caterpillar 216B3 (UNUSED)

Numéro de série: CAT0216BTPWM00363 | Heure: 5 | Lieu: United Arab Emirates | SKU: 798

## Key Features & Condition

| | |
|---|---|
| Safety Certification Label | N/A |
| Operator’s Manual | N/A |
| Equipment Parts Manual | N/A |
| Air Conditioning System | N/A |
| Emission Compliance Label | N/A |
| Quick Attachment Coupler | N/A |
| Horn Function | Yes |

## Operator Cabin Details

| | |
|---|---|
| Seat and Arm Support | Ok |
| Cab Doors & covers | N/A |
| Control Levers, Control Stick | Ok |
| Windows and Mirrors | Ok |
| Gauges | Ok |
| Warning alarms message | Ok |
| Washer, Wipers | N/A |
| Air Conditioning & Heating System | N/A |
| Cab Floor Covering | Ok |
| Cab Structure, Guard | Ok |
| Electrical System | Ok |

## Engine & Performance

| | |
|---|---|
| Fuel Injection Type | Mechanical |
| Engine Model | c2.2 |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Blowby | Normal |
| Exhaust System & Muffler | Ok |
| Belts & Air/Oil Filters | Ok |

**PANDE Auctions LLC**
Dubai, PO Box: 71530, Dubai, United Arab Emirates
Tel: +97148861125
www.PlantAndEquipment.com

| | |
|---|---|
| Smoke | Normal |
| Coolant | Ok |
| Leaks& seals | Ok |

**Exterior Condition & Visual Inspection**

| | |
|---|---|
| Main Frame and Lift Arm | Ok |
| Protective Covers & Sheets | Ok |
| Engine Door | Ok |
| Lights | Ok |
| Battery Check | Ok |
| Exterior Paint Condition | Ok |

**Hydraulic System**

| | |
|---|---|
| Hydraulic Leaks | Ok |
| Lift and Tilt Hydraulic Jack | Ok |
| Steering Hydraulic Orbital | Ok |
| Hydraulic Pumps and Valves | Ok |

**Limited Functional Testing & Operation**

| | |
|---|---|
| Steering Function Test | Ok |
| Skid steer Stall Test | Ok |
| Brake System Test | Ok |
| Attachment Pins | Ok |
| Final Drive Motors Test | Ok |

**Attachments**

| | |
|---|---|
| Attachments model | Bucket (0.36 $m^3$) |
| Size | W1530, H700, D420 mm |
| Bottom condition | Ok |
| Edge & teeth condition | Ok |
| Bucket side conditiion | Ok |
| Coupler status | Ok |

**Tires Estimated Remaining Life %**

| | |
|---|---|
| Front Right | 100% |
| Front Left | 100% |
| Rear Right | 100% |
| Rear Left | 100% |
| Size | 10.16.5 |
| Type | Tubless |
| wheel Rims & Nuts | Ok |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.